

**PENNSYLVANIA HISTORIC RESOURCE SURVEY FORM PHOTO/SITE PLAN SHEET**

Pennsylvania Historic and Museum Commission

Bureau of Historic Preservation

Box 1026, Harrisburg, PA 17108-1026

Survey Code/Tax Parcel/Other No.: 099 / 66 00 05833 00 5 Block-Unit #026-031

County: Montgomery

Municipality: Whitpain Township

Address: 336 Railroad Avenue

Historic Name/Other Name:

**SITE PLAN****PHOTO INFORMATION**

Number	Description of View	Direction of Camera
1	House – façade	
2	House – façade (right)	
3		
4		
5		
6		
Photographer Name: Robert Wise		Date: 1999
Negative Location: Robert Wise Consulting, Station Square 1, Suite 104, 37 N. Valley Road, Paoli PA 19301		

# PENNSYLVANIA HISTORIC RESOURCE SURVEY FORM - DATA SHEET

Pennsylvania Historical and Museum Commission, Bureau for Historic Preservation

89B

## IDENTIFICATION AND LOCATION

Survey Code: 099 Tax Parcel/Other No.: 66 00 05833 00 5 Block Unit #026-031

County: 1. Montgomery 091 2.

Municipality: 1. Whitpain Township 2.

Address: 336 Railroad Avenue Historic Name:

Other Name:

Owner Name/Address: Edgar V. & Anne B. Gibby 336 Railroad Avenue Ambler PA 19002

Owner Category: x Private Public-local Public-state Public-federal

Resource Category: x Building District Site Structure Object

Number/Aproximate Number of Resources Covered by This Form: 2

USGS Quad: 1. Lansdale 2.

UTM A. \_\_\_\_\_ C. \_\_\_\_\_

References: B. \_\_\_\_\_ D. \_\_\_\_\_

## HISTORIC AND CURRENT FUNCTIONS

Historic Function Category: Residence Subcategory: Dwelling Code:

A. 1889 1,788 SF Land 0.71 Acre Dwelling \_\_\_\_\_

B. \_\_\_\_\_

C. \_\_\_\_\_

D. \_\_\_\_\_

Particular Type: A. \_\_\_\_\_

B. \_\_\_\_\_

C. \_\_\_\_\_

D. \_\_\_\_\_

Current Function Category: Subcategory: Code:

A. Single Family Residence Dwelling \_\_\_\_\_

B. \_\_\_\_\_

C. \_\_\_\_\_

D. \_\_\_\_\_

## PHYSICAL DESCRIPTION

Architectural Classification: A. Colonial Revival \_\_\_\_\_

B. \_\_\_\_\_

D. \_\_\_\_\_

C. \_\_\_\_\_

Other: \_\_\_\_\_

Exterior Materials: Foundation \_\_\_\_\_ Roof \_\_\_\_\_ slate \_\_\_\_\_

Walls \_\_\_\_\_ stone \_\_\_\_\_ Walls \_\_\_\_\_

Other \_\_\_\_\_ Other \_\_\_\_\_

Structural System: 1. \_\_\_\_\_ 2. \_\_\_\_\_

Width 3 bay \_\_\_\_\_ Depth \_\_\_\_\_ Stories/Height 2.5 \_\_\_\_\_

## HISTORICAL INFORMATION

Year Built: ca. 1889 Additions/Alterations Dates: ca. ca.  
Basis for Dating: x Documentary Physical  
Explain: Tax records

Cultural/Ethnic Affiliation: 1. \_\_\_\_\_ 2. \_\_\_\_\_ Associated Individuals: 1. \_\_\_\_\_ 2.  
Associated Events: 1. \_\_\_\_\_ 2. \_\_\_\_\_ Architects/Engineers: 1. \_\_\_\_\_ 2.  
Builders: 1. \_\_\_\_\_ 2.

## MAJOR BIBLIOGRAPHICAL REFERENCES

## PREVIOUS SURVEY, DETERMINATIONS

### EVALUATION (Survey Director/Consultants Only)

Individual NR Potential: Yes x No Context(s): \_\_\_\_\_  
Contributes to Potential District Yes No District Name/Status: \_\_\_\_\_

**Classification:** This house is a Class II resource due to condition and architecture.

## THREATS

Threats: x 1. None 2. Public Development 3. Private Development 4. Neglect 5. Other

Explain:

## SURVEYOR INFORMATION

Surveyor Name/Title: Robert Wise Date: 6/16/2000  
Project Name: Whitpain Township Historic Resource Survey  
Organization: Robert Wise Consulting/Whitpain Township Telephone: (610) 722-5818  
Street and No.: Station Square 1, Suite 104, 37 North Valley Road  
City, State: Paoli, Pa Zip Code: 19301  
Additional Survey Documentation: n/a  
Associated Survey Codes: n/a

PENNSYLVANIA HISTORICAL RESOURCE SURVEY FORM  
NARRATIVE SHEET 89C

Pennsylvania Historical and Museum Commission  
Bureau for Historic Preservation

Survey Code: 099 Tax Parcel/Other No.: 66 00 05833 00 5 Block-Unit #026-031  
County: Montgomery 091 Municipality: Whitpain Township  
Address: 336 Railroad Avenue  
Historic/Other Name:

**PHYSICAL DESCRIPTION:**

This is a Colonial Revival house built of uncoursed stone. It is a three-bay, two and a half story house built c. 1889. The roof of this house is slate; it is an end gable roof with interior end chimneys corbeled near the top. Two shed roofed dormers are located on the main façade, each having a set of paired windows. The dormer roofs are supported by scroll sawn brackets. The second floor windows are double hung stone jack arches. There are no windows on the first floor façade; instead, three doors stand in the bays. There is a transom over the center door. A one story shed roof porch rests on four square columns to shade the doors. There is a two-story frame addition off the back of the house and a one story enclosed porch off the rear of the addition that is also frame. This house is in poor condition.

**Classification:** This house is a Class II resource due to condition and architecture.

