

PENNSYLVANIA HISTORIC RESOURCE SURVEY FORM PHOTO/SITE PLAN SHEET
Pennsylvania Historic and Museum Commission
Bureau of Historic Preservation
Box 1026, Harrisburg, PA 17108-1026

Survey Code/Tax Parcel/Other No.: 163 / 66 00 08227 00 5 Block-Unit #019-038

County: Montgomery

Municipality: Whitpain Township

Address: 1218 Walton Road

Historic Name/Other Name:

SITE PLAN

PHOTO INFORMATION



Number	Description of View	Direction of Camera
1	House – façade	
2	House – addition	
3	Carriage House	
4		
5		
6		
Photographer Name:	Robert Wise	Date: 1999
Negative Location:	Robert Wise Consulting, Station Square 1, Suite 104, 37 N. Valley Road, Paoli PA 19301	

PENNSYLVANIA HISTORIC RESOURCE SURVEY FORM - DATA SHEET

Pennsylvania Historical and Museum Commission, Bureau for Historic Preservation

89B

IDENTIFICATION AND LOCATION

Survey Code: 163 Tax Parcel/Other No.: 66 00 08227 00 5 Block Unit #019-038

County: 1. Montgomery 091 2.

Municipality: 1. Whitpain Township 2.

Address: 1218 Walton Road Historic Name:

Other Name:

Owner Name/Address: Frank A. & Nancy Devaux 1218 Walton Road Blue Bell PA 19422

Owner Category: Private Public-local Public-state Public-federal

Resource Category: Building District Site Structure Object

Number/Aproximate Number of Resources Covered by This Form: 2

USGS Quad: 1. Lansdale 2.

UTM A. _____ C. _____

References: B. _____ D. _____

HISTORIC AND CURRENT FUNCTIONS

Historic Function Category: **Subcategory:** **Code:**

A. Residence 1880 2,494 SF Land 5.16 Acre Dwelling _____

B. _____

C. _____

D. _____

Particular Type: A. _____

B. _____

C. _____

D. _____

Current Function Category: **Subcategory:** **Code:**

A. Single Family Residence Dwelling _____

B. _____

C. _____

D. _____

PHYSICAL DESCRIPTION

Architectural Classification: A. Victorian Gothic _____

B. _____

D. _____

C. _____

Other: _____

Exterior Materials: Foundation _____ Roof _____ asphalt shingles _____

Walls _____ stucco _____ Walls _____

Other _____ Other _____

Structural System: 1. _____ 2. _____

Width 3 bay _____ Depth _____ Stories/Height 2.5 _____

HISTORICAL INFORMATION

Year Built: ca. 1880 Additions/Alterations Dates: ca. ca.
Basis for Dating: x Documentary Physical
Explain: Tax records

Cultural/Ethnic Affiliation: 1. _____ 2. _____ Associated Individuals: 1. _____ 2.
Associated Events: 1. _____ 2. _____ Architects/Engineers: 1. _____ 2.
Builders: 1. _____ 2.

MAJOR BIBLIOGRAPHICAL REFERENCES

PREVIOUS SURVEY, DETERMINATIONS

EVALUATION (Survey Director/Consultants Only)

Individual NR Potential: Yes x No Context(s): _____
Contributes to Potential District Yes No District Name/Status: _____

Classification: While this house is in good to excellent condition, the additions and the relocated front door make it a Class II resource.

THREATS

Threats: x 1. None 2. Public Development 3. Private Development 4. Neglect 5. Other

Explain:

SURVEYOR INFORMATION

Surveyor Name/Title: Robert Wise Date: 6/16/2000
Project Name: Whitpain Township Historic Resource Survey
Organization: Robert Wise Consulting/Whitpain Township Telephone: (610) 722-5818
Street and No.: Station Square 1, Suite 104, 37 North Valley Road
City, State: Paoli, Pa Zip Code: 19301
Additional Survey Documentation: n/a
Associated Survey Codes: n/a

PENNSYLVANIA HISTORICAL RESOURCE SURVEY FORM
NARRATIVE SHEET 89C

Pennsylvania Historical and Museum Commission
Bureau for Historic Preservation

Survey Code: 163 Tax Parcel/Other No.: 66 00 08227 00 5 Block-Unit #019-038
County: Montgomery 091 Municipality: Whitpain Township
Address: 1218 Walton Road
Historic/Other Name:

PHYSICAL DESCRIPTION:

This Victorian Gothic house and stable house are in excellent condition. The house, built c. 1880, is a two and a half story, three bay structure. It has end gables and a strong centered gable with an arched window. The house is clad in gray stucco, has interior end chimneys, and sports a nice pent roof. The windows on the third floor gable end are two over four double hung while the first and second floor windows are six over six double hung. None of the windows have shutters. There are two additions: a one story stucco-clad addition on a gable end and one rear two-story addition.

Associated Resource:

A building associated with this house is a one and a half story stable or carriage house. This building sports a similar cross-gable profile as the house. A prominent element on the stable is the decorative verge board, although it is clad in machined shingles.

Classification: While this house is in good to excellent condition, the additions and the relocated front door make it a Class II resource.



