

PENNSYLVANIA HISTORIC RESOURCE SURVEY FORM PHOTO/SITE PLAN SHEET

Pennsylvania Historic and Museum Commission

Bureau of Historic Preservation

Box 1026, Harrisburg, PA 17108-1026

Survey Code/Tax Parcel/Other No.: 166 / 66 00 08173 00 5 Block-Unit #020-057

County: Montgomery

Municipality: Whitpain Township

Address: 1533 Walton Road

Historic Name/Other Name:

SITE PLAN**PHOTO INFORMATION****Direction of Camera**

Number	Description of View	Direction of Camera
1	House	
2		
3		
4		
5		
6		

Photographer Name: Robert Wise Date: 1999

Negative Location: Robert Wise Consulting, Station Square 1, Suite 104,
37 N. Valley Road, Paoli PA 19301

PENNSYLVANIA HISTORIC RESOURCE SURVEY FORM - DATA SHEET

Pennsylvania Historical and Museum Commission, Bureau for Historic Preservation

89B

IDENTIFICATION AND LOCATION

Survey Code: 166 Tax Parcel/Other No.: 66 00 08173 00 5 Block Unit #020-057

County: 1. Montgomery 091 2.

Municipality: 1. Whitpain Township 2.

Address: 1533 Walton Road Historic Name:

Other Name:

Owner Name/Address: Robert Maurice & Susan M. Silverstein 1533 Walton Road Blue Bell PA 19422

Owner Category: Private Public-local Public-state Public-federal

Resource Category: Building District Site Structure Object

Number/Approximate Number of Resources Covered by This Form: 2

USGS Quad: 1. Lansdale 2.

UTM A. _____ C. _____

References: B. _____ D. _____

HISTORIC AND CURRENT FUNCTIONS

Historic Function Category: **Subcategory:** **Code:**

A. Residence 1895 3,062 SF Land 3.00 Acre Dwelling _____

B. _____

C. _____

D. _____

Particular Type: A. _____

B. _____

C. _____

D. _____

Current Function Category: **Subcategory:** **Code:**

A. Single Family Residence Dwelling _____

B. _____

C. _____

D. _____

PHYSICAL DESCRIPTION

Architectural Classification: A. Federal _____

B. _____

D. _____

C. _____

Other: _____

Exterior Materials: Foundation _____ Roof _____

Walls stucco _____ Walls _____

Other _____ Other _____

Structural System: 1. _____ 2. _____

Width _____ Depth _____ Stories/Height 3 _____

HISTORICAL INFORMATION

Year Built: ca. 1895 Additions/Alterations Dates: ca. ca.
Basis for Dating: x Documentary Physical
Explain: Tax records

Cultural/Ethnic Affiliation: 1. _____ 2. _____ Associated Individuals: 1. _____ 2.
Associated Events: 1. _____ 2. _____ Architects/Engineers: 1. _____ 2.
Builders: 1. _____ 2.

MAJOR BIBLIOGRAPHICAL REFERENCES

PREVIOUS SURVEY, DETERMINATIONS

EVALUATION (Survey Director/Consultants Only)

Individual NR Potential: Yes x No Context(s): _____
Contributes to Potential District Yes No District Name/Status: _____

Classification: While this house is in excellent condition, the additions make it a Class II resource.

THREATS

Threats: x 1. None 2. Public Development 3. Private Development 4. Neglect 5. Other

Explain:

SURVEYOR INFORMATION

Surveyor Name/Title: Robert Wise Date: 6/16/2000
Project Name: Whitpain Township Historic Resource Survey
Organization: Robert Wise Consulting/Whitpain Township Telephone: (610) 722-5818
Street and No.: Station Square 1, Suite 104, 37 North Valley Road
City, State: Paoli, Pa Zip Code: 19301
Additional Survey Documentation: n/a
Associated Survey Codes: n/a

PENNSYLVANIA HISTORICAL RESOURCE SURVEY FORM
NARRATIVE SHEET 89C

Pennsylvania Historical and Museum Commission
Bureau for Historic Preservation

Survey Code: 166 Tax Parcel/Other No.: 66 00 08173 00 5 Block-Unit #020-057
County: Montgomery 091 Municipality: Whitpain Township
Address: 1533 Walton Road
Historic/Other Name:

PHYSICAL DESCRIPTION:

This secluded house is an example of Federal architecture. It consists of a large two and a half story, three bay core with additions to produce an H-plan building. The core is an end gable house with two interior end chimneys. The house is clad in stucco. The windows are floor specific: the first floor windows are six over nine double hung with shutters; the second floor windows are six over six double hung with shutters; the third floor windows are three over three double hung without shutters. A simple one story porch adorns the façade. The additions are also stucco-clad. They maintain the first and second story window treatment.

Associated Resource: An associated carriage house is in poor shape.

Classification: While this house is in excellent condition, the additions make it a Class II resource.

