

PENNSYLVANIA HISTORIC RESOURCE SURVEY FORM PHOTO/SITE PLAN SHEET
Pennsylvania Historic and Museum Commission
Bureau of Historic Preservation
Box 1026, Harrisburg, PA 17108-1026

Survey Code/Tax Parcel/Other No.: 155 / 66 00 06745 00 2 Block-Unit #009-004

County: Montgomery

Municipality: Whitpain Township

Address: 1951 Skippack Pike

Historic Name/Other Name:

SITE PLAN

PHOTO INFORMATION



| Number | Description of View | Direction of Camera |
|--------------------|---|---------------------|
| 1 | House – façade | |
| 2 | House – rear | |
| 3 | Garage | |
| 4 | | |
| 5 | | |
| 6 | | |
| Photographer Name: | Robert Wise | Date: 1999 |
| Negative Location: | Robert Wise Consulting, Station Square 1, Suite 104, 37 N. Valley Road, Paoli PA 19301 | |

PENNSYLVANIA HISTORIC RESOURCE SURVEY FORM - DATA SHEET

Pennsylvania Historical and Museum Commission, Bureau for Historic Preservation

89B

IDENTIFICATION AND LOCATION

Survey Code: 155 Tax Parcel/Other No.: 66 00 06745 00 2 Block Unit #009-004

County: 1. Montgomery 091 2.

Municipality: 1. Whitpain Township 2.

Address: 1951 Skippack Pike Historic Name:

Other Name:

Owner Name/Address: Frederic A. & Brenda C. Mayer 129 Runnymede Drive Lansdale PA 19446

Owner Category: Private Public-local Public-state Public-federal

Resource Category: Building District Site Structure Object

Number/Approximate Number of Resources Covered by This Form: 3

USGS Quad: 1. Lansdale 2.

UTM A. _____ C. _____

References: B. _____ D. _____

HISTORIC AND CURRENT FUNCTIONS

Historic Function Category: **Subcategory:** **Code:**

A. Residence 1890 1,287 SF Land 4.21 Acre Dwelling _____

B. _____

C. _____

D. _____

Particular Type: A. _____

B. _____

C. _____

D. _____

Current Function Category: **Subcategory:** **Code:**

A. Single Family Residence Dwelling _____

B. _____

C. _____

D. _____

PHYSICAL DESCRIPTION

Architectural Classification: A. Vernacular _____

B. _____

D. _____

C. _____

Other: _____

Exterior Materials: Foundation _____ Roof _____ asphalt shingles _____

Walls _____ stucco _____

Other _____

Walls _____

Other _____

Structural System: 1. _____ 2. _____

Width 2 bays / 15 feet Depth 30 feet Stories/Height 2

HISTORICAL INFORMATION

Year Built: ca. 1890 Additions/Alterations Dates: ca. ca.
Basis for Dating: x Documentary Physical
Explain: Tax records

Cultural/Ethnic Affiliation: 1. _____ 2. _____ Associated Individuals: 1. _____ 2.
Associated Events: 1. _____ 2. _____ Architects/Engineers: 1. _____ 2.
Builders: 1. _____ 2.

MAJOR BIBLIOGRAPHICAL REFERENCES

PREVIOUS SURVEY, DETERMINATIONS

EVALUATION (Survey Director/Consultants Only)

Individual NR Potential: Yes x No Context(s): _____
Contributes to Potential District Yes No District Name/Status: _____

Classification: Due to changes, such as the French doors, the house is Class II.

THREATS

Threats: x 1. None 2. Public Development 3. Private Development 4. Neglect 5. Other

Explain:

SURVEYOR INFORMATION

Surveyor Name/Title: Robert Wise Date: 6/16/2000
Project Name: Whitpain Township Historic Resource Survey
Organization: Robert Wise Consulting/Whitpain Township Telephone: (610) 722-5818
Street and No.: Station Square 1, Suite 104, 37 North Valley Road
City, State: Paoli, Pa Zip Code: 19301
Additional Survey Documentation: n/a
Associated Survey Codes: n/a

PENNSYLVANIA HISTORICAL RESOURCE SURVEY FORM
NARRATIVE SHEET 89C

Pennsylvania Historical and Museum Commission
Bureau for Historic Preservation

Survey Code: 155 Tax Parcel/Other No.: 66 00 06745 00 2 Block-Unit #009-004
County: Montgomery 091 Municipality: Whitpain Township
Address: 951 Skippack Pike
Historic/Other Name:

PHYSICAL DESCRIPTION:

This house, reportedly built in 1890, may actually date to the post-Civil War era. The two story, stucco covered house has an front end-gabled, asphalt shingled roof, side entrance, and a pair of French doors facing Skippack Pike. The house consists of the core, a single story, rear addition, also stucco-covered, and walled front porch, consisting of coursed stonework. The façade facing the pike is symmetrical with two 2x2 double hung sash windows located above the two glass French doors. There is no ornamentation. The side entrance originally had a gabled hood. Today it consists of a solid paneled door with single pane transom. Windows on the first and second floors are 2x2 double hung sash. Those windows, like the two attic windows above, are asymmetrical. The house appears to be in poor condition.

Associated Buildings: There are two outbuildings on the property: a stucco-covered, two bay garage with entrance extension, and a small, stucco covered shed. Both buildings have asphalt shingled, end gabled roofs.

Classification: Due to changes, such as the French doors, the house is Class II.



