

Public Works Monthly Report November 2017

Emphasis this month was on the following:

Highway Division:

- **Annual Road Maintenance Program** – Public Works is beginning to work on roadways scheduled for our 2018 road resurfacing program. We are currently assessing conditions in preparation to schedule needed repairs to road surfaces, storm sewers, sanitary sewers, and curbing. The Township contracted with an outside firm to take cores of Cathcart Road to help us plan for its resurfacing. (See attached)
- **Street Sign Upgrades** – Township staff continues to replace and repair existing street signs and regulatory signs on many Township roadways. This task is ongoing to bring signage in compliance with new state and federal reflectivity standards. Most regulatory signs are being upgraded on all newly resurfaced roadways. Township staff is tree trimming around many street signs throughout the Township (see attached)
- **Street Sweeping** - Township staff continues its annual street sweeping program. During the month approximately 17 cubic yards of debris was picked up on Township roadways. (see attached)
- **Olson House Renovations** – Township staff is assisting other divisions of Public Works in making needed repairs to this facility. A major portion of these repairs are being coordinated with outside contractors and vendors. (see attached)
- **Line Painting** – Township staff and outside contractors painted traffic lines on various township roadways during the month. (See Attached)
- **Salt Brine Making** – Township Highway staff along with Parks Division staff have begun to ready our brine making equipment. This included making sure all equipment was tested and made about eight thousand gallons of brine for winter use.

Parks Division:

- **Parks Maintenance** – Township Park Staff continues to maintain and make repairs to Township active parks equipment as needed. Active playing fields are being maintained as needed for fall use. Township roadsides are being mowed as scheduled. Staff is getting ready for winter operations. (see attached)

Building Maintenance Division:

- **Buildings Maintenance** – All Township buildings were maintained as scheduled and as needed. (See attached)
- **Olson House Renovations** – Township staff are supplementing the work done by outside contractors by performing work on both the interior and exterior of the Olson House. (see attached)

- **Administration Bldg Repairs** – Township staff continues to perform routine maintenance as scheduled and as needed. (see attached)

Sewer Division:


- **Pump Station Maintenance** – Township staff maintained all seven Township owned sewer pump stations as needed. (see attached)
- **Butler Pike Station Repairs** - During the month of October, the pump station had two of its pumps go down requiring emergency after hour repairs to be made. Township staff is currently working with outside contractors to make permanent repairs to the station.
- **Sewer Maintenance** –Staff continues to prepare for the 2018 road resurfacing project. This work includes sewer line inspection, televising, and manhole restoration. Township staff assisted other Township staff in the renovations of the Olson House Project. Staff continues to meet with PennDOT regarding the relocation of sanitary sewers in conjunction with the 202-widening project. Staff is working on a new water line installation at Center Square Park. This line will service the new WRA clubhouse. (see attached)

Equipment Maintenance:

- All Township equipment and vehicles were maintained as needed. Public Works received our new budgeted Case Loader during the month. This loader replaces our 202 Volvo Loader (see attached)


Public Works Administration:

- Administrative staff is working on several projects which include overseeing the Center Square Park Clubhouse/Concession stand construction, Prophecy Creek Manor House renovations, Olson House renovations, and the Route 202 Widening Project utility modifications.


Ronald J. Cione, DPW

Date	POC	Remarks
11/1/2017		Replaced two M.H. lids (Hemlock, Kurt). Epoxy-seal training for manhole repair.
11/2/2017		
11/3/2017	8	PA one calls #8. Blow levee at station.
11/4/2017		
11/5/2017		
11/9/2017	11	Check pump stations. Check PA one calls (11). Clean up leaves at Twp Line North
11/7/2017	14	Check pump stations. Check PA one calls (14). Check pump stations. Check PA one calls (9). Start cleaning Twp Line station (inside). Worked at Butler Pike station w/ Wayne from Godwin Pump
11/8/2017	8	Check pump stations. Check PA one calls (12). Check trouble spots.
11/9/2017	12	
11/10/2017		
11/11/2017		PA one call. Rice Beams Church Rd water repair 11:30 AM.
11/12/2017		
11/13/2017	17	PA one calls #17
11/14/2017	14	PA one calls #14. Work on trouble spot list. Hed a blockage on #73
11/15/2017	5	PA one calls #5
11/16/2017	11	PA one calls #11
11/17/2017		
11/18/2017		6:50 AM alarm from Twp Line station power off noon on normal. Ran 3
11/19/2017		2:30 PM emergency one call 802 Valley Rd replace poles (no conflict)
11/20/2017	27	Check pump stations. Check PA one calls (27) (vial?) back up pump at Beale Rd (4'), winterize easement machine
11/21/2017		Check pump station. Check PA one calls (7) Check trouble spots
11/22/2017	7	
11/23/2017		
11/24/2017		
11/25/2017		12:00 PA one call emergency 1040 Dekalb Pk, water leak repaired JA
11/26/2017		
11/27/2017	10	PA one calls #10
11/28/2017	11	PA one calls #11
11/29/2017	14	Checked pump stations. Check PA one calls (14). Filled Godwin Pump at Butler Pike (diesel)
11/30/2017	9	Check pump stations. PA one calls (9)
	Total POC	178

Work Order #	Description	Due Date	Work Tasks	Activity	Notes
BM-2017-1.14	HELPING PARKS WORK ON GATI	11/2/2017	Painting	Activity Info	WALLS AND CEILINGS IN KITCHEN AND IN THE RESTROOM
BM-2017-1.15	OLSEN HOSE	11/3/2017	Painting Building Repairs Inside Cleaning	Activity Info Activity 2 Info Activity 3 Info	STARTED TO PUT THE FINISH ON THE WALLS WENT AROUND AND PUT BOXES TOGETHER FOR ELECTIONS CLEANING OUT BASEMENT AREA
BM-2017-1.16	OLSEN HOUSE CLEAN UP	11/6/2017	Cleaning Cleaning Cleaning	Activity Info Activity 2 Info Activity 3 Info	WE SWEEP REMOVE AND SCRAPED FLOORS WE THRU OUT ALL WOOD AND DEBR STARTED TO PAINT TRIM
BM-2017-1.18	OLSEN HOUSE	11/8/2017	Cleaning Building Repairs Outside Building Repairs Outside	Activity Info Activity 2 Info Activity 3 Info	SWEEP AND CLEANED EVERYTHING OUT SHUTTERS ARRIVED WE TOOK ALL NEW SHUTTERS AND MOVE TO THE 2ND FLOOR OF OLSEN HOUSE AND ALL THE OLD ONES TO THE BASEMENT CLEAN UP THE ELECTED SIGNS AND PUT THEM IN THERE BOXES



Work Order Report

Total: 30


ID	Type	Status	Address Location	Type of Work	Start Date	Cost
HWY-2017-234	Daily Work Log - New Highway Division	New	Shop	BMT - Brine Making/Treatment	11/1/2017	\$128.00
	Address Location: Shop Weather Condition: Cloudy Type of Work: BMT - Brine Making/Treatment Temperature: 55 FH					
HWY-2017-235	Daily Work Log - New Highway Division	New	Lewis Lane	LP - Line Painting, SRR - Signs	11/1/2017	\$194.50
	Address Location: Lewis Lane Weather Condition: Cloudy - Cool Address Location: Twp Line North Weather Condition: Cloudy - Cool Type of Work: LP - Line Painting, SRR - Signs (Install) Temperature: 56 FH Type of Work: LP - Line Painting, SRR - Signs (Install) Temperature: 56 FH					
HWY-2017-236	Daily Work Log - New Highway Division	New	Cook Track	MNT - Maintenance	11/2/2017	\$256.00
	Address Location: Cook Track Weather Condition: Cool Type of Work: MNT - Maintenance Temperature: 70 FH					
HWY-2017-237	Daily Work Log - New Highway Division	New	Garage/Cooke Track	BMT - Brine Making/Treatment	11/2/2017	\$128.00
	Address Location: Garage/Cooke Track Weather Condition: Sunny Type of Work: BMT - Brine Making/Treatment Temperature: 72 FH					
HWY-2017-238	Daily Work Log - New Highway Division	New	Shop	MNT - Maintenance	11/3/2017	\$320.00
	Address Location: Shop Weather Condition: Nice Type of Work: MNT - Maintenance Temperature: 75 FH					
HWY-2017-239	Daily Work Log - New Highway Division	New	1533 Sullivan	MNT - Maintenance	11/6/2017	\$128.00



Work Order Report

Total: 30


ID#	Type	Status	Address Location	Type of Work	Start Date	Cost
Address Location: 1533 Sullivan Weather Condition: Cool						
HWY-2017-240	Daily Work Log - New Highway Division	New	Shop - Garage	MNT - Maintenance Temperature: 60 FH	11/6/2017	\$320.00
Address Location: Shop - Garage Weather Condition: Cloudy						
HWY-2017-241	Daily Work Log - New Highway Division	New	North Wales	SRR - Signs Type of Work: MNT - Maintenance Temperature: 68 FH	11/7/2017	\$16.00
Address Location: North Wales Weather Condition: Rain						
HWY-2017-242	Daily Work Log - New Highway Division	New	Cook track	MNT - Maintenance Type of Work: SRR - Signs Temperature: 50 FH	11/7/2017	\$24.00
Address Location: Cook track Weather Condition: Overcast						
HWY-2017-243	Daily Work Log - New Highway Division	New	Shop	MNT - Maintenance Type of Work: MNT - Maintenance Temperature: 56 FH	11/7/2017	\$256.00
Address Location: Shop Weather Condition: Rain						
HWY-2017-244	Daily Work Log - New Highway Division	New	223 Oak St	SRR - Signs (Replace) Type of Work: MNT - Maintenance Temperature: 60 FH	11/7/2017	\$128.00
Address Location: 223 Oak St Weather Condition: Overcast						
HWY-2017-245	Daily Work Log - New Highway Division	New	223 Oak St	SRR - Signs (Replace) Type of Work: SRR - Signs (Replace) Temperature: 50 FH	11/7/2017	\$128.00



Work Order Report

Total: 30


ID	Type	Status	Address/Location	Type of Work	Start Date	Cost
Address Location: 223 Oak St Weather Condition: Overcast						
HWY-2017-246	Daily Work Log - New Highway Division	New	Center Square Park	MNT - Maintenance	11/9/2017	\$289.00
Address Location: Center Square Park Weather Condition: Cool						
HWY-2017-247	Daily Work Log - New Highway Division	New	Shop	MNT - Maintenance	11/8/2017	\$128.00
Address Location: Shop Weather Condition: Cold						
HWY-2017-248	Daily Work Log - New Highway Division	New	Cooke Track (8hrs)	MNT - Maintenance	11/13/2017	\$128.00
Address Location: Cooke Track (8hrs) Weather Condition: Rain						
HWY-2017-249	Daily Work Log - New Highway Division	New	960 Wentz Rd (8 hrs)	MNT - Maintenance	11/13/2017	\$192.00
Address Location: 960 Wentz Rd (8 hrs) Weather Condition: Rain						
HWY-2017-250	Daily Work Log - New Highway Division	New	404 - 432 - 44 Railroad Ave	SRR - Signs (Replace)	11/14/2017	\$48.00
Address Location: 404 - 432 - 44 Railroad Ave Weather Condition: Cloudy						
HWY-2017-251	Daily Work Log - New Highway Division	New	Maple St, Rt. 73, Cherry Rd	LP - Line Painting, SRR -	11/14/2017	\$160.00



Work Order Report

Total: 30


ID#	Type	Status	Address Location	Type of Work	N/A	Start Date	Cost
Address Location: Maple St, Rt. 73, Cherry Rd Weather Condition: Cloudy - Cold Type of Work: LP - Line Painting, SRR - Signs, MNT - Maintenance Temperature: 48 FH							
HWY-2017-252	Daily Work Log - New Highway Division	New	960 Wentz Rd	MNT - Maintenance		11/14/2017	\$256.00
Address Location: 960 Wentz Rd Weather Condition: Cool Type of Work: MNT - Maintenance Temperature: 50 FH							
HWY-2017-253	Daily Work Log - New Highway Division	New	Jolly Rd	MNT - Maintenance		11/15/2017	\$128.00
Address Location: Jolly Rd Weather Condition: Sunny Type of Work: MNT - Maintenance Temperature: 50 FH							
HWY-2017-254	Daily Work Log - New Highway Division	New	Shop and cook tract	MNT - Maintenance		11/15/2017	\$192.00
Address Location: Shop and cook tract Weather Condition: Sun/Clouds Type of Work: MNT - Maintenance Temperature: 50 FH							
HWY-2017-255	Daily Work Log - New Highway Division	New	Cook tract	MNT - Maintenance		11/15/2017	\$128.00
Address Location: Cook tract Weather Condition: Cool Type of Work: MNT - Maintenance Temperature: 50 FH							
HWY-2017-256	Daily Work Log - New Highway Division	New	Pempeton, Henkel & McCoy	MNT - Maintenance		11/16/2017	\$266.00
Address Location: Pempeton, Henkel & McCoy Weather Condition: Cool Type of Work: MNT - Maintenance Temperature: 50 FH							
HWY-2017-257	Daily Work Log - New Highway Division	New	Cook Tract (8hrs)	MNT - Maintenance		11/17/2017	\$320.00



Work Order Report

Total: 30

ID	Type	Status	Address/Location	Type of Work	Start Date	Cost
Address Location: Cook Track (8hrs) Weather Condition: Cold Type of Work: MNT - Maintenance Temperature: 40 FH						
HWY-2017-258	Daily Work Log - New Highway Division	New	Shop - 1098 Skippack Pike	MNT - Maintenance	11/22/2017	\$192.00
Address Location: Shop - 1098 Skippack Pike (8hrs) Weather Condition: Rain/Cold Type of Work: MNT - Maintenance Temperature: 40 FH						
HWY-2017-259	Daily Work Log - New Highway Division	New	Cathcart Rd (8hrs)	MNT - Maintenance	11/21/2017	\$256.00
Address Location: Cathcart Rd (8hrs) Weather Condition: Cool Type of Work: MNT - Maintenance Temperature: 50 FH						
HWY-2017-260	Daily Work Log - New Highway Division	New	960 Wentz Rd (8 hrs)	MNT - Maintenance	11/27/2017	\$128.00
Address Location: 960 Wentz Rd (8 hrs) Weather Condition: Nice Type of Work: MNT - Maintenance Temperature: 40 FH						
HWY-2017-261	Daily Work Log - New Highway Division	New	Cook Track	MNT - Maintenance	11/28/2017	\$128.00
Address Location: Cook Track Weather Condition: Sunny Type of Work: MNT - Maintenance Temperature: 50 FH						
HWY-2017-265	Daily Work Log - New Highway Division	New	Shop	MNT - Maintenance	11/30/2017	\$192.00
Address Location: Shop Weather Condition: Sun/clouds Type of Work: MNT - Maintenance Temperature: 50 FH						
HWY-2017-266	Daily Work Log - New Highway Division	New	960 wentz	MNT - Maintenance	11/30/2017	\$192.00



Work Order Report

Total: 30

ID	Type	Status	Address Location	Type of Work	N/A	Start Date	Cost
----	------	--------	------------------	--------------	-----	------------	------

Address Location: 960 wentz
 Weather Condition: Cool
 Type of Work: MNT - Maintenance
 Temperature: 40 FH

Total Address Location: 0 | Total Type of Work: 0 | Total: 0 Total: \$5,349.50



Work Order Report

Total: 19

ID	Type	Status	N/A	N/A	Start Date	Cost	
WO-P-109	Parks	Completed	N/A	N/A	11/1/2017	\$384.00	
		Belfry, Centre Square Park, Erbs Mill, Stony Creek Park: Sports Park (Marino), Twp. Wood Chip Bin, West Side Court, West Side Park, Wurts, Yost Notes: Mow, trim and weed-eat. Park: Wentz Run Park Notes: Install new switchback gates on walking trail.					
WO-P-110	Parks	Completed			11/2/2017	\$384.00	
		Parks Activity Group: Grasscutting Work Done By: Mike Bowe, Michael Gilbert, Pat Reilly Parks Activity Group: Park Maintenance Work Done By: Stan Dull, Chris Matozzo					
WO-P-111	Parks	Completed			11/3/2017	\$320.00	
		Park: Armentrout, Bateson, Nicolet, Prophecy Creek Park Notes: Mow, trim and weed-eat. Parks Activity Group: Grasscutting Work Done By: Mike Bowe, Michael Gilbert, Pat Reilly Parks Activity Group: Park Maintenance Work Done By: Michael Gilbert, Pat Reilly Parks Activity Group: Pesticides Work Done By: Stan Dull, Chris Matozzo Parks Activity Group: Equipment Repair Work Done By: Stan Dull, Mike Bowe Parks Activity Group: Miscellaneous Work Done By: Michael Gilbert, Chris Matozzo Parks Activity Group: Park Maintenance Work Done By: Chris Matozzo					
WO-P-112	Parks	Completed			11/6/2017	\$384.00	
		960 Wentz Road, Armentrout, Centre Square Park, PECO, Prophecy Creek Park, Stony Creek Sports Park (Marino), Wentz Run Park, West Side Court, West Side Park Park: Empty trash and dog waste, re-fill dog waste bags. Park: 960 Wentz Road, Prophecy Creek Park Notes: Prep leaf collection equipment. Equipment maintenance and repairs.					
WO-P-113	Parks	Completed			11/7/2017	\$384.00	
		Parks Activity Group: Trash Collection Work Done By: Stan Dull, Mike Bowe, Michael Gilbert, Pat Reilly, Chris Matozzo Parks Activity Group: Equipment Repair Work Done By: Stan Dull, Mike Bowe, Michael Gilbert, Pat Reilly, Chris Matozzo					



Work Order Report

Total: 19


ID#	Type	Status	N/A	N/A	Start Date	Cost
WO-P-114	Parks	Completed			11/8/2017	\$384.00
		Park: Wentz Run Park Notes: Mow and vacuum leaves. Park: Wentz Run Park Notes: Winterize/blow-out tot lot drinking fountain. Park: 960 Wentz Road Notes: Prep parks winter equipment. Park: 960 Wentz Road Notes: Deliver 600 leaf bags to Admin. Bldg.			Parks Activity Group: Grasscutting Work Done By: Mike Bowe, Michael Gilbert, Pat Reilly, Chris Matozzo Parks Activity Group: Park Maintenance Work Done By: Stan Dull Parks Activity Group: Miscellaneous Work Done By: Stan Dull Parks Activity Group: Miscellaneous Work Done By: Stan Dull, Michael Gilbert	
		Park: 960 Wentz Road, Wentz Run Park Notes: Trim bushes and hedges/clean up flower beds and courtyard areas. Park: 960 Wentz Road, Wentz Run Park Notes: Mow and vacuum leaves. Park: Wentz Run Park Notes: Winterize drinking fountain at concession stand, turn on heat in concession stand and bathrooms.			Parks Activity Group: Park Maintenance Work Done By: Stan Dull, Mike Bowe, Michael Gilbert, Pat Reilly, Chris Matozzo Parks Activity Group: Grasscutting Work Done By: Mike Bowe, Michael Gilbert, Pat Reilly, Chris Matozzo Parks Activity Group: Miscellaneous Work Done By: Stan Dull	
WO-P-115	Parks	Completed			11/9/2017	\$256.00
		Park: 960 Wentz Road Notes: Equip. Maintenance, sharpen and install leaf mulching blades. Park: Stony Creek Sports Park (Marino) Notes: Mow, trim and weed-eat. Mulch and vacuum leaves.			Parks Activity Group: Equipment Repair Work Done By: Stan Dull, Mike Bowe, Michael Gilbert, Chris Matozzo Parks Activity Group: Grasscutting Work Done By: Stan Dull, Michael Gilbert, Chris Matozzo	
WO-P-116	Parks	Completed			11/13/2017	\$192.00
		Park: 960 Wentz Road, Armentrout, Centre Square Park, PECO, Prophecy Creek Park, Stony Creek Sports Park (Marino), Wentz Run Park, West Side Court, West Side Park Notes: Empty trash and dog waste, re-fill dog waste bags. Park: 960 Wentz Road Notes: Equip. maint. and repairs, work in shop. Park: 960 Wentz Road, West Side Park Notes: Deliver 600 leaf bags to Admin. Bldg.			Parks Activity Group: Trash Collection Work Done By: Stan Dull, Pat Reilly Parks Activity Group: Equipment Repair Work Done By: Stan Dull, Pat Reilly Parks Activity Group: Miscellaneous Work Done By: Stan Dull, Pat Reilly	
WO-P-117	Parks	Completed			11/14/2017	\$320.00



Work Order Report

Total: 19

ID	Type	Status	N/A	N/A	Start Date	Cost
WO-P-118	Parks	Completed			11/15/2017	\$384.00
<p>Park: 960 Wentz Road Notes: Equip. maint. & repairs, work in shop. Park: Olson Notes: Mulch state rep sign. Park: Wentz Run Park Notes: Repair switchback gate.</p>						
<p>Parks Activity Group: Equipment Repair Work Done By: Stan Dull, Michael Gilbert, Pat Reilly, Chris Matozzo Parks Activity Group: Park Maintenance Work Done By: Stan Dull, Michael Gilbert, Chris Matozzo Parks Activity Group: Park Maintenance Work Done By: Stan Dull, Michael Gilbert, Chris Matozzo</p>						
WO-P-119	Parks	Completed			11/16/2017	\$384.00
<p>Park: 960 Wentz Road, Wentz Run Park Notes: Mow, trim, weed-eat, mulch and vacuum leaves. Park: 960 Wentz Road Notes: Equip. maint. & repairs. Park: Wentz Run Park Notes: Re-fuel portable lights on soccer fields. Park: Wentz Run Park Notes: Install posts for mile-marker signs along trail.</p>						
<p>Parks Activity Group: Grasscutting Work Done By: Stan Dull, Mike Bowe, Michael Gilbert, Pat Reilly, Chris Matozzo Parks Activity Group: Equipment Repair Work Done By: Stan Dull, Mike Bowe Parks Activity Group: Miscellaneous Work Done By: Stan Dull Parks Activity Group: Park Maintenance Work Done By: Stan Dull, Chris Matozzo</p>						
WO-P-120	Parks	Completed			11/17/2017	\$256.00
<p>Park: 960 Wentz Road, Wentz Run Park Notes: Mow, trim, weed-eat, mulch and vacuum leaves. Park: Stony Creek Sports Park (Marino), Wissahickon Notes: Mow, trim and weed-eat. Park: Wentz Run Park Notes: Install posts for mile-marker signs along walking trail. Park: 960 Wentz Road Notes: Deliver 500 leaf bags.</p>						
<p>Parks Activity Group: Grasscutting Work Done By: Mike Bowe, Michael Gilbert, Pat Reilly, Chris Matozzo Parks Activity Group: Grasscutting Work Done By: Mike Bowe, Michael Gilbert, Pat Reilly, Chris Matozzo Parks Activity Group: Park Maintenance Work Done By: Stan Dull, Chris Matozzo Parks Activity Group: Miscellaneous Work Done By: Michael Gilbert</p>						
WO-P-121	Parks	Completed			11/20/2017	\$192.00
<p>Park: Prophecy Creek Park Notes: Mow, trim, weed-eat grass, mulch and vacuum leaves.</p>						
<p>Parks Activity Group: Grasscutting Work Done By: Mike Bowe, Michael Gilbert, Pat Reilly, Chris Matozzo</p>						



Work Order Report

Total: 19


ID#	Type	Status	N/A	N/A	Start Date	Cost
WO-P-122	Parks	Completed			11/21/2017	\$192.00
Park: 960 Wentz Road Notes: Bobcat mini-excavator training. 960 Wentz Road, Armentrout, Centre Square Park, PECO, Prophecy Creek Park, Stony Creek Sports Park (Marino), Wentz Run Park, West Side Court, West Side Park Park: Wentz Run Park, West Side Court, West Side Park Notes: Empty trash and dog waste, re-fill dog waste bags. Notes: Deliver 600 leaf bags. Parks Activity Group: Miscellaneous Work Done By: Stan Dull, Michael Gilbert						
WO-P-123	Parks	Completed			11/22/2017	\$128.00
Park: 960 Wentz Road, Wentz Run Park Notes: Mow, mulch and vacuum leaves. Park: 960 Wentz Road Notes: Deliver 500 leaf bags. Parks Activity Group: Grasscutting Work Done By: Stan Dull, Michael Gilbert Parks Activity Group: Miscellaneous Work Done By: Stan Dull, Michael Gilbert						
WO-P-124	Parks	Completed			11/27/2017	\$192.00
Park: 960 Wentz Road Notes: Equipment maintenance and repairs. Park: Wentz Run Park Notes: Mow, mulch and vacuum leaves. Parks Activity Group: Equipment Repair Work Done By: Stan Dull, Michael Gilbert Parks Activity Group: Grasscutting Work Done By: Stan Dull, Michael Gilbert Parks Activity Group: Grasscutting Work Done By: Stan Dull, Michael Gilbert Parks Activity Group: Equipment Repair Work Done By: Stan Dull, Michael Gilbert, Chris Matozzo Parks Activity Group: Trash Collection Work Done By: Stan Dull, Michael Gilbert, Chris Matozzo						
WO-P-125	Parks	Completed			11/28/2017	\$192.00
Park: 960 Wentz Road, Armentrout, Centre Square Park, PECO, Prophecy Creek Park, Stony Creek Sports Park (Marino), Wentz Run Park, West Side Court, West Side Park Notes: Empty trash and dog waste, re-fill dog waste bags. Park: Wentz Run Park Notes: Mow, mulch and vacuum leaves. Parks Activity Group: Grasscutting Work Done By: Stan Dull, Michael Gilbert, Chris Matozzo						
WO-P-126	Parks	Completed			11/29/2017	\$192.00
Park: Wentz Run Park Notes: Mow, mulch and vacuum leaves. Parks Activity Group: Grasscutting Work Done By: Stan Dull, Michael Gilbert, Chris Matozzo						



Work Order Report

Total: 19

ID#	Type	Status	N/A	N/A	Start Date	Cost
WO-P-12Z	Parks	Completed			11/30/2017	\$192.00
		Notes: Stony Creek Sports Park (Marino), Wentz Run Park Notes: Mow, mulch and vacuum leaves. Park: 960 Wentz Road Notes: Deliver 500 leaf bags to Admin. Bldg.				
		Notes: Sharpen blades on mowing equip.				
		Park: Prophecy Creek Park, Wissahickon Notes: Mow, mulch and vacuum leaves.				
		Parks Activity Group: Equipment Repair Work Done By:: Stan Dull, Michael Gilbert, Chris Matozzo				
		Parks Activity Group: Grasscutting Work Done By:: Stan Dull, Michael Gilbert, Chris Matozzo				
		Parks Activity Group: Miscellaneous Work Done By:: Michael Gilbert, Chris Matozzo				
					Total : 0	Total : 0
						Total : \$5,312.00



Work Order Report

Total: 2


ID#	Type	Status	N/A	N/A	Start Date	Cost
GT-17-11	Grease Trap Inspections	New	N/A	N/A	11/2/2017	\$0.00
Business Name: East Cuisine Food Grease Trap In Compliance? Yes Notes: all good at this Location. Date Last Inspected: 2017-11-01T00:00:00.0						
GT-17-12	Grease Trap Inspections	New			11/2/2017	\$0.00
Business Name: Michael's Pizza Food Grease Trap In Compliance? Yes Notes: One grease trap on site.						
Total : 0					Total :	0
Total : 0					Total :	\$0.00



Work Order Report

Total: 3

ID#	Type	Status	N/A	N/A	Sweep Date	Cost
SS-2017-70	Street Sweeping	New	N/A	N/A	11/15/2017	\$64.00
Number of Times Tank 2 Emptied: 2 Total Yards Disposed: 6 YD # of Times Dumped: 2						
SS-2017-71	Street Sweeping	New			11/16/2017	\$64.00
Number of Times Tank 2.5 Emptied: 2 Total Yards Disposed: 5 YD # of Times Dumped: 2						
SS-2017-72	Street Sweeping	New			11/17/2017	\$64.00
Number of Times Tank 2.5 Emptied: 3 Millings: 0 YD # of Times Millings 0 Dumped: 3 Total Yards Disposed: 6 YD # of Times Dumped: 3						
Total : 0					Total : 0	Total : 0
Total : 0					Total : 0	Total : \$192.00



Work Order Report

Total: 26

ID#	Type	Status	N/A	N/A	Start Date	Cost
2017-11	Daily Sewer Sheet	Completed	N/A	N/A	11/1/2017	\$0.00

Number of PA One Calls Today: 0

work on manhole 1033 hemlock drive manhole #
Notes: A6-1553. Had training on Epoxy-tech application in manhole

Sewer Activity Group: New Sewer Main Inspections

Sewer Activity Group: Miscellaneous

Work Done By:: Ron Fricker, Tom Albertson, Ed White, Jeff Antunes, Rob Draper

785 Arbor Way Woodlands:

Inspection: 8" Inch SDR-26 sewer main going in and three new manholes going as well.

Duke's Root Control is back to finish with the root control will be done today.

we will have done 18,000 Lineal feet of 8inch sewer main this year.

Work Done By:: Gus Belmont


Sewer Activity Group: Pump Station Inspection

Work Done By:: Tom Albertson, Rob Draper

Location of Work: Township Line Road Pump Station, Mermaid Run Pump Station, Devonshires Pump Station, Township Line Road North Pump Station, Beale Road Pump Station, North Wales Road Pump Station, Addison Reserve

Notes: did not get to one calls do to training.

2017-13	Daily Sewer Sheet	New			11/3/2017	\$0.00
---------	-------------------	-----	--	--	-----------	--------



Work Order Report

Total: 26

ID	Type	Status	N/A	Start Date	Cost
			N/A		

Number of PA One Calls 8
Today:

Location of Work: Township Line Road Pump Station, Mermaid Run Pump Station, Devonshires Pump Station, Township Line Road North Pump Station, Beale Road Pump Station, North Wales Road Pump Station, Addison Reserve

Notes: Blew leaves at North wales Station. Sucked out and plunged clogged lateral at 721 W Skipback pike. cleaned sidewalk and grassy area where lateral overflowed.

Work Done By: Gus Belmont, Ron Fricker, Tom Albertson, Ed White, Jeff Antunes, Rob Draper

Location of Work: Township Line Road North Pump Station
Repair stand pipe to force main on pump #1 cut out ball check and bad section of line re plumbed.
Notes: Installed new supports and brackets. Saw cut driveway at center square sports park for electric crossing. Cleaned up from jobs.

Sewer Activity Group: Pump Station Inspection
Work Done By: Tom Albertson, Rob Draper

Sewer Activity Group: Miscellaneous
Work Done By: Ron Fricker, Ed White, Jeff Antunes

2017-16	Daily Sewer Sheet	New		11/6/2017	\$0.00
---------	-------------------	-----	--	-----------	--------

Number of PA One Calls 11
Today:

Location of Work: Township Line Road Pump Station, Mermaid Run Pump Station, Devonshires Pump Station, Township Line Road North Pump Station, Beale Road Pump Station, North Wales Road Pump Station, Addison Reserve


Notes: Check pump stations, clean up leaves at townshipline north
Location of Work: Township Line Road Pump Station, Township Line Road North Pump Station

Sewer Activity Group: Miscellaneous

Sewer Activity Group: Pump Station Inspection
Work Done By: Doug Taylor, Tom Albertson

Notes: Pulled Pump #2 and worked on cleaning the Check Valve at Township Line North, Went to Denney Electric to pick up parts for the Pump Stations, Dropped off Saw at Township Line Erbs Mill, Went to Gil's Quarry for 10 Tons of Clean Screenings for Center Square Park.
Work Done By: Ron Fricker, Ed White, Jeff Antunes, Rob Draper

2017-17	Daily Sewer Sheet	New		11/7/2017	\$0.00
---------	-------------------	-----	--	-----------	--------



Work Order Report

Total: 26

ID#	Type	Status	N/A	Start Date	Cost
-----	------	--------	-----	------------	------

Number of PA One Calls Today: 14

Location of Work: Township Line Road Pump Station, Mermaid Run Pump Station, Devonshires Pump Station, Township Line Road North Pump Station, Beale Road Pump Station, North Wales Road Pump Station, Addison Reserve

Notes: check pump stations, check pa one calls
Sewer Activity Group: Miscellaneous

Sewer Activity Group: Pump Station Inspection
Work Done By:: Doug Taylor, Tom Albertson

Notes: Trench across driveway for electric and communication conduits at center square park .Installed conduit and back filled.
Work Done By:: Gus Belmont, Ron Fricker, Doug Taylor, Tom Albertson, Ed White, Jeff Antunes, Rob Draper

2017-18 Daily Sewer Sheet New 11/8/2017 \$0.00

Number of PA One Calls Today: 8


Location of Work: Township Line Road Pump Station, Mermaid Run Pump Station, Devonshires Pump Station, Township Line Road North Pump Station, Beale Road Pump Station, North Wales Road Pump Station, Addison Reserve

Notes: check pump stations, check pa one calls, start cleaning inside township line station
Location of Work: Devonshires Pump Station

Sewer Activity Group: Pump Station Inspection
Work Done By:: Doug Taylor, Tom Albertson

Notes: Work with xylem godwin to winterize backup pumps. worked with Wayne from Godwin on walk around at stations to access emergency pump hook ups for stations in case of emergency .
Work Done By:: Ron Fricker, Ed White, Jeff Antunes, Rob Draper


2017-19 Daily Sewer Sheet New 11/9/2017 \$0.00



Work Order Report

Total: 26


ID#	Type	Status	N/A	Start Date	Cost
2017-20	Daily Sewer Sheet	New		11/10/2017	\$0.00
<p>Number of PA One Calls Today: 12</p> <p>Location of Work: Township Line Road Pump Station, Mermaid Run Pump Station, Devonshires Pump Station, Township Line Road North Pump Station, Beale Road Pump Station, North Wales Road Pump Station, Addison Reserve</p> <p>Notes: check pump stations, check pa one calls, check trouble spots</p> <p>Location of Work: Devonshires Pump Station</p> <p>Sewer Activity Group: Miscellaneous</p> <p>Location of Work: Devonshires Pump Station</p> <p>Notes: Repair force main connection . Connection came apart while pumping . Repaired with new clamps.</p>					
<p>Sewer Activity Group: Pump Station Inspection</p> <p>Work Done By:: Doug Taylor, Tom Albertson</p> <p>Notes: Picked up heat tape from Denny electric for Devonshire Pump station. Picked up concrete blankets from Cosimo Riccioli. Winterized hoses for pumps at Devonshire pump station.</p> <p>Work Done By:: Ron Fricker, Ed White, Jeff Antunes, Rob Draper</p> <p>Sewer Activity Group: Miscellaneous</p> <p>Work Done By:: Ron Fricker, Tom Albertson, Ed White, Rob Draper</p>					
2017-21	Daily Sewer Sheet	New		11/11/2017	\$0.00
<p>Number of PA One Calls Today: 0</p> <p>Location of Work: Township Line Road Pump Station, Mermaid Run Pump Station, Devonshires Pump Station, Township Line Road North Pump Station, Beale Road Pump Station, North Wales Road Pump Station, Addison Reserve</p> <p>Notes: check pump stations</p>					
<p>Sewer Activity Group: Pump Station Inspection</p> <p>Work Done By:: Doug Taylor, Tom Albertson</p>					



Work Order Report

Total: 26


ID#	Type	Status	N/A	Start Date	Cost
2017-22	Daily Sewer Sheet	New		11/12/2017	\$0.00
Number of PA One Calls Today: 0 Location of Work: Township Line Road Pump Station, Mermaid Run Pump Station, Devonshires Pump Station, Township Line Road North Pump Station, Beale Road Pump Station, North Wales Road Pump Station, Addison Reserve Notes: check pump stations. open bathrooms (not locked) ,sweep floors and take out trash at north wales rd. sports park Sewer Activity Group: Pump Station Inspection Work Done By:: Doug Taylor, Tom Albertson					
2017-23	Daily Sewer Sheet	New		11/13/2017	\$0.00
Number of PA One Calls Today: 17 Location of Work: Township Line Road Pump Station, Mermaid Run Pump Station, Devonshires Pump Station, Township Line Road North Pump Station, North Wales Road Pump Station, Addison Reserve Notes: check pump stations,open bathrooms at north wales sports park (not locked), sweep up trash and empty trash cans . Pa one call 11:30 am water repair bomes chrich rd marked tom Sewer Activity Group: Pump Station Inspection Work Done By:: Doug Taylor, Tom Albertson					
2017-24	Daily Sewer Sheet	New		11/14/2017	\$0.00
Number of PA One Calls Today: 17 Location of Work: Township Line Road Pump Station, Mermaid Run Pump Station, Devonshires Pump Station, Township Line Road North Pump Station, Beale Road Pump Station, North Wales Road Pump Station, Addison Reserve Notes: Check pump stations pa one calles Sewer Activity Group: Pump Station Inspection Work Done By:: Doug Taylor, Tom Albertson					



Work Order Report

Total: 26


ID#	Type	Status	N/A	Start Date	Cost
<p>Number of PA One Calls Today: 14</p> <p>Location of Work: Township Line Road Pump Station, Mermaid Run Pump Station, Devonshires Pump Station, Township Line Road North Pump Station, Beale Road Pump Station, North Wales Road Pump Station, Addison Reserve</p> <p>Notes: Work on trouble spot list</p> <p>Location of Work: North Wales Road Pump Station</p> <p>Sewer Activity Group: Flushing Lines</p> <p>Work Done By: Doug Taylor, Tom Albertson</p>					
<p>Number of PA One Calls Today: 5</p> <p>Location of Work: Township Line Road Pump Station, Mermaid Run Pump Station, Devonshires Pump Station, Township Line Road North Pump Station, Beale Road Pump Station, North Wales Road Pump Station, Addison Reserve</p> <p>Notes: Check pump. Stations. Pa one calls work on trouble spot list finished replace manhole lid on 73 manhole # b5-692.</p> <p>Location of Work: Township Line Road Pump Station, Mermaid Run Pump Station, Devonshires Pump Station, Township Line Road North Pump Station, Beale Road Pump Station, North Wales Road Pump Station, Addison Reserve, Sewer Easements</p> <p>Sewer Activity Group: Equipment Repair</p> <p>Work Done By: Doug Taylor, Tom Albertson</p>					
2017-25	Daily Sewer Sheet	New		11/15/2017	\$0.00
2017-26	Daily Sewer Sheet	New		11/16/2017	\$0.00



Work Order Report

Total: 26

ID#	Type	Status	N/A	Start Date	Cost
2017-27	Daily Sewer Sheet	New		11/17/2017	\$0.00
<p>Number of PA One Calls Today: 11</p> <p>Location of Work: Township Line Road Pump Station, Mermaid Run Pump Station, Devonshires Pump Station, Township Line Road North Pump Station, Beale Road Pump Station, North Wales Road Pump Station, Addison Reserve</p> <p>Notes: Check pump station Pa one calles clean up at stations</p> <p>Location of Work: Devonshires Pump Station</p> <p>Work Done By: Doug Taylor, Tom Albertson</p> <p>Notes: Went to Penn Hollow to get a breather line for echo hand held leaf blower. Finished winterizing Devonshire pump station.</p> <p>Work Done By: Ron Fricker, Ed White, Jeff Antunes, Rob Draper</p>					
2017-28	Daily Sewer Sheet	New		11/18/2017	\$0.00
<p>Number of PA One Calls Today: 0</p> <p>Location of Work: Township Line Road Pump Station, Mermaid Run Pump Station, Devonshires Pump Station, Township Line Road North Pump Station, Beale Road Pump Station, North Wales Road Pump Station, Addison Reserve</p> <p>Notes: attended epwcoa meeting in pottstown.</p> <p>Work Done By: Ron Fricker, Doug Taylor, Tom Albertson, Ed White, Rob Draper</p> <p>Work Done By: Ron Fricker, Tom Albertson</p> <p>Sewer Activity Group: Pump Station Inspection</p> <p>Work Done By: Doug Taylor, Jeff Antunes</p>					
2017-29	Daily Sewer Sheet	New		11/19/2017	\$0.00



Work Order Report

Total: 26

ID#	Type	Status	N/A	Start Date	Cost
			N/A		

Number of PA One Calls Today: 0

Sewer Activity Group: Pump Station Inspection
Work Done By: Doug Taylor, Jeff Antunes

Location of Work: Township Line Road Pump Station, Mermaid Run Pump Station, Devonshires Pump Station, Township Line Road North Pump Station, Beale Road Pump Station, North Wales Road Pump Station, Addison Reserve
check pump stations, sweep floor and empty trash cans at the sports park. (N. Wales Rd.) 6:50 am.
Notes: alarm call at Township line station, power is off power is now on. everything is now normal.

2017-30	Daily Sewer Sheet	New		11/20/2017	\$0.00
---------	-------------------	-----	--	------------	--------

Number of PA One Calls Today: 27


Sewer Activity Group: Pump Station Inspection
Work Done By: Doug Taylor, Tom Albertson

Location of Work: Township Line Road Pump Station, Mermaid Run Pump Station, Devonshires Pump Station, Township Line Road North Pump Station, Beale Road Pump Station, North Wales Road Pump Station, Addison Reserve
Notes: check pump stations, check pa one calls, bobcat training
Location of Work: Sewer Easements

Notes: Bobcat training . Flagged and marked all our sewer on cathcart.

Work Done By: Ed White, Jeff Antunes, Rob Draper


2017-31	Daily Sewer Sheet	New		11/21/2017	\$0.00
---------	-------------------	-----	--	------------	--------



Work Order Report

Total: 26


ID#	Type	Status	N/A	Start Date	Cost
2017-33	Daily Sewer Sheet	New		11/23/2017	\$0.00
<p>Number of PA One Calls Today: 11</p> <p>Location of Work: Township Line Road Pump Station, Mermaid Run Pump Station, Devonshires Pump Station, Township Line Road North Pump Station, Beale Road Pump Station, Addison Reserve</p> <p>Notes: check pump stations, check pa one calls, check fuel in Godwin pump at Beale Rd. station (4 inches). winterize easement machine at Township Line station.</p> <p>Notes: Cleaned up the shop washed S-10, and used Epoxy tech in manhole # A6-1513 on Hemlock.</p> <p>Work Done By:: Ed White, Jeff Antunes, Rob Draper</p> <p>Sewer Activity Group: Pump Station Inspection Work Done By:: Doug Taylor, Tom Albertson</p>					
2017-34	Daily Sewer Sheet	New		11/24/2017	\$0.00
<p>Number of PA One Calls Today: 0</p> <p>Location of Work: Township Line Road Pump Station, Mermaid Run Pump Station, Devonshires Pump Station, Township Line Road North Pump Station, Beale Road Pump Station, North Wales Road Pump Station, Addison Reserve</p> <p>Notes: check pump stations</p> <p>Sewer Activity Group: Pump Station Inspection Work Done By:: Doug Taylor, Jeff Antunes</p>					
2017-35	Daily Sewer Sheet	New		11/25/2017	\$0.00
<p>Number of PA One Calls Today: 0</p> <p>Location of Work: Township Line Road Pump Station, Mermaid Run Pump Station, Devonshires Pump Station, Township Line Road North Pump Station, Beale Road Pump Station, North Wales Road Pump Station, Addison Reserve</p> <p>Notes: check pump stations</p> <p>Sewer Activity Group: Pump Station Inspection Work Done By:: Doug Taylor, Jeff Antunes</p>					



Work Order Report

Total: 26

ID#	Type	Status	N/A	Start Date	Cost
2017-36	Daily Sewer Sheet	New		11/26/2017	\$0.00
<p>Number of PA One Calls Today: 0</p> <p>Location of Work: Township Line Road Pump Station, Mermaid Run Pump Station, Devonshires Pump Station, Township Line Road North Pump Station, Beale Road Pump Station, North Wales Road Pump Station, Addison Reserve Notes: check pump stations, sweep bathrooms and empty trash cans at the sports park</p> <p>Sewer Activity Group: Pump Station Inspection Work Done By:: Doug Taylor, Jeff Antunes</p>					
2017-37	Daily Sewer Sheet	New		11/27/2017	\$0.00
<p>Number of PA One Calls Today: 10</p> <p>Location of Work: Township Line Road Pump Station, Mermaid Run Pump Station, Devonshires Pump Station, Township Line Road North Pump Station, Beale Road Pump Station, North Wales Road Pump Station, Addison Reserve Notes: check pump station and clean up at stations Sewer Activity Group: New Sewer Main Inspections</p> <p>Sewer Activity Group: Pump Station Inspection Work Done By:: Doug Taylor, Tom Albertson</p> <p>Notes: 626 Penilyn Blue Bell Pike was hooked up to the sanitary sewer on 11/27/2017 Work Done By:: Gus Belmont Work Done By:: Ron Fricker, Jeff Antunes</p>					



Work Order Report

Total: 26

ID#	Type	Status	N/A	N/A	Start Date	Cost
2017-38	Daily Sewer Sheet	New	N/A	N/A	11/28/2017	\$0.00

Number of PA One Calls Today: 11

Location of Work: Township Line Road Pump Station, Mermaid Run Pump Station, Devonshires Pump Station, Township Line Road North Pump Station, Beale Road Pump Station, North Wales Road Pump Station, Addison Reserve

Notes: check emergency equipment
 Notes: work on pump to devonshire station .Meet with lancaster truck and hippo to go over S-4 truck specs.

Work Done By:: Ron Fricker, Jeff Antunes

Location of Work: Devonshires Pump Station

Notes: Called out to high water in wet well at devonshire station around 4:05 pm .found that the temporary hook up for the pump station bypass had come apart . Re hooked up line and put a kicker in to help stop the separation . finished work around 6:30.

Sewer Activity Group: Pump Station Inspection
 Work Done By:: Doug Taylor, Tom Albertson

Work Done By:: Ron Fricker, Tom-Albertson

2017-39	Daily Sewer Sheet	New			11/29/2017	\$0.00
---------	-------------------	-----	--	--	------------	--------


Number of PA One Calls Today: 14

Location of Work: Township Line Road Pump Station, Devonshires Pump Station, Township Line Road North Pump Station, Beale Road Pump Station, North Wales Road Pump Station, Addison Reserve

Notes: check pump stations, check pa one calls, filled Godwin pump with fuel (butler pk.)

Sewer Activity Group: Pump Station Inspection
 Work Done By:: Doug Taylor, Tom Albertson

2017-40	Daily Sewer Sheet	New			11/30/2017	\$0.00
---------	-------------------	-----	--	--	------------	--------



Work Order Report

Total: 26

ID	Type	Status	N/A	N/A	Start Date	Cost
----	------	--------	-----	-----	------------	------

Number of PA One Calls Today: 9

Location of Work: Township Line Road Pump Station, Mermaid Run Pump Station, Devonshires Pump Station, Township Line Road North Pump Station, Beale Road Pump Station, North Wales Road Pump Station, Addison Reserve

Notes: check pump stations, check pa one calls, clean up leaves at township line north

Sewer Activity Group: Pump Station Inspection
Work Done By: Doug Taylor, Rob Draper

Total : 0

Total : 0

Total : 0

Total \$0.00