PENNSYLVANIA HISTORIC RESOURCE SURVEY FORM PHOTO/SITE PLAN SHEET

Pennsylvania Historic and Museum Commission
Bureau of Historic Preservation
Box 1026, Harrisburg, PA 17108-1026

Survey Code/Tax Parcel/Other No.: 068 / 66-00-04729-00-2 Block Unit #022-015 County: Montgomery

Municipality: Whitpain Township Address: 31 Norristown Road

Historic Name/Other Name:

SITE PLAN

PHOTO INFORMATION



Number	Description of View	Direction of Camera
1	House and Garage	
2	House – façade (right)	
3	House – façade (left)	
4		
5		
6		

Photographer Name: Robert Wise Date: 1999

Negative Location: Robert Wise Consulting, Station Square 1, Suite 104, 37 N. Valley Road, Paoli PA 19301

PENNSYLVANIA HISTORIC RESOURCE SURVEY FORM - DATA SHEET

Pennsylvania Historical and Museum Commission, Bureau for Historic Preservation

IDENTIFICATION AND LOCATION

Survey Code: 068 Tax Parcel/Other No.: 66-00-04093-00-80 Block Unit #009A-018
County: 1. Montgomery 091 2.
Municipality: 1. Whitpain Township 2.
Address: 31 Norristown Road Historic Name:
Other Name:
Owner Name/Address: Lewis & Kathleen Canouse 31 Norristown Rd Blue Bell PA 19422
Owner Category: x Private ___Public-local ___Public-state ___Public-federal
Resource Category: x Building ___District ___Site ___Structure ___Object
Number/Approximate Number of Resources Covered by This Form: 2
USGS Quad: 1. Lansdale 2.
UTM References: A. ___ C.
B. ___ D.

HISTORIC AND CURRENT FUNCTIONS

Historic Function **Category:**	**Subcategory:**	**Code:**
A. Residence	Dwelling	
B.		
C.		
D.		

Particular Type: A. ___
B. ___
C. ___
D. ___

Current Function Category:	**Subcategory:**	**Code:**
A. Single Family Residence	Dwelling	
B.		
C.		
D.		

PHYSICAL DESCRIPTION

Architectural Classification: A. Colonial Revival
B. C.
D. Other:

Exterior Materials: Foundation Roof asphalt shingle
Walls stone Walls
Other Other
Structural System: 1. 2.
Width 3 bay / 30 feet Depth Stories/Height 2.5

HISTORICAL INFORMATION

Year Built:____ca.__1920_____ Additions/Alterations Dates:__ca.____ca.___
Basis for Dating:_x__ Documentary ____Physical
Explain: Tax records

Cultural/Ethnic Affiliation: 1. _____2. _____Associated Individuals: 1. _____2.
Associated Events: 1._____2. _____Architects/Engineers: 1._____2.
Builders: 1. _____2.

MAJOR BIBLIOGRAPHICAL REFERENCES

PREVIOUS SURVEY, DETERMINATIONS

EVALUATION (Survey Director/Consultants Only)

Individual NR Potential: ___Yes _x__No Context(s):_____
Contributes to Potential District ___Yes ___No District Name/Status:

Classification: This well-maintained house is a Class II resource.

THREATS

Threats: _x__ 1. None 2. Public Development 3. Private Development 4. Neglect 5. Other

Explain:

SURVEYOR INFORMATION

Surveyor Name/Title: Robert Wise Date: 6/16/2000
Project Name: Whitpain Township Historic Resource Survey
Organization: Robert Wise Consulting/Whitpain Township Telephone: (610) 722-5818
Street and No.: Station Square 1, Suite 104, 37 North Valley Road
City, State: Paoli, Pa Zip Code: 19301
Additional Survey Documentation: n/a
Associated Survey Codes: n/a

PENNSYLVANIA HISTORICAL RESOURCE SURVEY FORM
NARRATIVE SHEET 89C

Pennsylvania Historical and Museum Commission
Bureau for Historic Preservation

Survey Code: 068 Tax Parcel/Other No.: 66-00-04093-00-80 Block Unit #009A-018
County: Montgomery 091 Municipality: Whitpain Township
Address: 31 Norristown Road
Historic/Other Name:

PHYSICAL DESCRIPTION:

This Colonial Revival house borrows many elements from houses built prior to the American Revolution. It is a two and a half story house 25 x 30 with three bays, built c. 1920. It has an interior end chimney in one of the two end gables and nice molded eaves. The house was constructed with uncoursed stone. It has two gabled roof dormers and fanlights in the gable ends. A nice pedimented entry porch rests upon square columns and shades a door with fine sidelights. A one story stone addition on one side of the façade balances a secluded hipped-roof porch on the other side of the house.

Associated Resource: (Garage) Associated with this house is a one and a half story two-car garage.

Classification: This well-maintained house is a Class II resource due to the gabled additions on the left end.