

PENNSYLVANIA HISTORIC RESOURCE SURVEY FORM PHOTO/SITE PLAN SHEET

Pennsylvania Historic and Museum Commission

Bureau of Historic Preservation
Box 1026, Harrisburg, PA 17108-1026

Survey Code/Tax Parcel/Other No.: 094 / 66-00-05218-00-8

Block 016 Unit 008

County: Montgomery


Municipality: Whitpain Township

Address: Penllyn Blue Bell Pike

Historic Name/Other Name: _____

SITE PLAN

PHOTO INFORMATION



Number	Description of View	Direction of Camera
1	House – façade	
2		
3		
4		
5		
6		

Photographer Name: Robert Wise Date: 1999

Negative Location: Robert Wise Consulting, Station Square 1, Suite 104, 37 N. Valley Road, Paoli PA 19301

PENNSYLVANIA HISTORIC RESOURCE SURVEY FORM - DATA SHEET

Pennsylvania Historical and Museum Commission, Bureau for Historic Preservation

89B

IDENTIFICATION AND LOCATION

Survey Code: 094 Tax Parcel/Other No.: 66-00-05218-00-8 Block 016 Unit 008

County: 1. Montgomery 091 2.

Municipality: 1. Whitpain Township 2.

Address: Penllyn Blue Bell Pike Historic Name:

Other Name:

Owner Name/Address: Charles & Joan Davis 191 Penllyn Blue Bell Pike Blue Bell PA 19422

Owner Category: Private Public-local Public-state Public-federal

Resource Category: Building District Site Structure Object

Number/Approximate Number of Resources Covered by This Form: 1

USGS Quad: 1. Lansdale 2.

UTM A. _____ C. _____

References: B. _____ D. _____

HISTORIC AND CURRENT FUNCTIONS

Historic Function Category: Subcategory: Code:

A. Residence Dwelling -----

B. -----

C. -----

D. -----

Particular Type: A. _____

B. _____

C. _____

D. _____

Current Function Category: Subcategory: Code:

A. Single Family Residence Dwelling -----

B. -----

C. -----

D. -----

PHYSICAL DESCRIPTION

Architectural Classification: A. Victorian -----

B. -----

D. -----

Exterior Materials: Foundation asphalt shingles

Walls asphalt shingles

Other asphalt shingles

Structural System: 1. asphalt shingles 2.

Width 20' Depth 20' Stories/Height 2.5

HISTORICAL INFORMATION

Year Built: ___ ca. _____ Additions/Alterations Dates: ___ ca. ___ ca. ___

Basis for Dating: Documentary Physical

Explain: Tax records

Cultural/Ethnic Affiliation: 1. _____ 2. _____ Associated Individuals: 1. _____ 2.

Associated Events: 1. _____ 2. _____ Architects/Engineers: 1. _____ 2.

Builders: 1. _____ 2. _____

MAJOR BIBLIOGRAPHICAL REFERENCES

PREVIOUS SURVEY, DETERMINATIONS

EVALUATION (Survey Director/Consultants Only)

Individual NR Potential: ___ Yes No Context(s): _____

Contributes to Potential District Yes No District Name/Status:

Classification: This house is in good condition, yet the alterations make it a Class II resource.

THREATS

Threats: 1. None 2. Public Development 3. Private Development 4. Neglect 5. Other

Explain:

SURVEYOR INFORMATION

Surveyor Name/Title: Robert Wise Date: 6/16/2000

Project Name: Whitpain Township Historic Resource Survey

Organization: Robert Wise Consulting/Whitpain Township Telephone: (610) 722-5818

Street and No.: Station Square 1, Suite 104, 37 North Valley Road

City, State: Paoli, Pa Zip Code: 19301

Additional Survey Documentation: n/a

Associated Survey Codes: n/a

PENNSYLVANIA HISTORICAL RESOURCE SURVEY FORM
NARRATIVE SHEET 89C

Pennsylvania Historical and Museum Commission
Bureau for Historic Preservation

Survey Code: 094 Tax Parcel/Other No.: 66-00-05218-00-8 Block 016 Unit 008
County: Montgomery 091 Municipality: Whitpain Township
Address: Penllyn Blue Bell Pike
Historic/Other Name:

PHYSICAL DESCRIPTION:

This house across from the Cedarbrook Country Club is an example of Victorian complexity. It is a mix of an octagonal tower, a front end gambrel roof, and differing porches. Windows come in different shapes and sizes, but none of them have shutters. There is one exterior chimney. The roof is covered with asphalt shingles. There is a large front porch over the main entrance with a balcony over top.

Classification: This house is in good condition, yet the alterations make it a Class II resource.

