

PENNSYLVANIA HISTORIC RESOURCE SURVEY FORM PHOTO/SITE PLAN SHEET
 Pennsylvania Historic and Museum Commission
 Bureau of Historic Preservation
 Box 1026, Harrisburg, PA 17108-1026

Survey Code/Tax Parcel/Other No.: 052 / 66 00 04327 00 8 Block-Unit #023-015 County: Montgomery
 Municipality: Whitpain Township Address: 222 Morris Road
 Historic Name/Other Name: _____

SITE PLAN

PHOTO INFORMATION

No photo available

Number	Description of View	Direction of Camera
1		
2		
3		
4		
5		
6		
Photographer Name:	Robert Wise	Date: 1999
Negative Location:	Robert Wise Consulting, Station Square 1, Suite 104, 37 N. Valley Road, Paoli PA 19301	

PENNSYLVANIA HISTORIC RESOURCE SURVEY FORM - DATA SHEET

Pennsylvania Historical and Museum Commission, Bureau for Historic Preservation

89B

IDENTIFICATION AND LOCATION

Survey Code: 052 Tax Parcel/Other No.: 66.00 04327.00 8 Block Unit #023-015

County: 1. Montgomery 091 2.

Municipality: 1. Whitpain Township 2.

Address: 222 Morris Road Historic Name:

Other Name:

Owner Name/Address: Kenneth D. III & Gretchen Farragut 222 Morris Road Ambler PA 19002

Owner Category: Private Public-local Public-state Public-federal

Resource Category: Building District Site Structure Object

Number/Approximate Number of Resources Covered by This Form: 1

USGS Quad: 1. Lansdale 2.

UTM A. _____ C.

References: B. _____ D.

HISTORIC AND CURRENT FUNCTIONS

Historic Function Category: _____ Subcategory: _____ Code: _____

A. Residence 7,548 SF Land 9.27 Acre Dwelling _____

B. _____

C. _____

D. _____

photo missing

Particular Type: A. _____

B. _____

C. _____

D. _____

Current Function Category: _____ Subcategory: _____ Code: _____

A. Single Family Residence Dwelling _____

B. _____

C. _____

D. _____

PHYSICAL DESCRIPTION

Architectural Classification: A. Colonial _____

B. _____ C. _____

D. _____ Other: _____

Exterior Materials: Foundation _____ Roof _____

Walls stucco _____ Walls _____

Other _____ Other _____

Structural System: 1. _____ 2. _____

Width _____ Depth _____ Stories/Height _____

HISTORICAL INFORMATION

Year Built: ca. Additions/Alterations Dates: ca. ca.
Basis for Dating: Documentary Physical
Explain: Tax records

Cultural/Ethnic Affiliation: 1. 2. Associated Individuals: 1. 2.
Associated Events: 1. 2. Architects/Engineers: 1. 2.
Builders: 1. 2.

MAJOR BIBLIOGRAPHICAL REFERENCES

PREVIOUS SURVEY, DETERMINATIONS

EVALUATION (Survey Director/Consultants Only)

Individual NR Potential: Yes No Context(s):
Contributes to Potential District Yes No District Name/Status:

Classification: Although in excellent condition, the house includes several additions and thus is Class II.

THREATS

Threats: 1. None 2. Public Development 3. Private Development 4. Neglect 5. Other

Explain:

SURVEYOR INFORMATION

Surveyor Name/Title: Robert Wise Date: 6/16/2000
Project Name: Whitpain Township Historic Resource Survey
Organization: Robert Wise Consulting/Whitpain Township Telephone: (610) 722-5818
Street and No.: Station Square 1, Suite 104, 37 North Valley Road
City, State: Paoli, Pa Zip Code: 19301
Additional Survey Documentation: n/a
Associated Survey Codes: n/a

PENNSYLVANIA HISTORICAL RESOURCE SURVEY FORM
NARRATIVE SHEET 89C

Pennsylvania Historical and Museum Commission
Bureau for Historic Preservation

Survey Code: 052 Tax Parcel/Other No.: 66 00 04327 00 8 Block-Unit #023-015
County: Montgomery 091 Municipality: Whitpain Township
Address: 222 Morris Road
Historic/Other Name:

PHYSICAL DESCRIPTION:

Victorian Gothic house with several additions. Core is stone and stucco. Roof is front end gable. Including additions, the house is approximately 75' long and 25' wide. Walls are stucco.

Associated Resource: Garage. Block garage, stucco clad. (C)

Classification: Although in excellent condition, the house includes several additions and thus is Class II.