

PENNSYLVANIA HISTORIC RESOURCE SURVEY FORM PHOTO/SITE PLAN SHEET

Pennsylvania Historic and Museum Commission

Bureau of Historic Preservation

Box 1026, Harrisburg, PA 17108-1026

Survey Code/Tax Parcel/Other No.: 098 / 66-00-05830-00-8 Block Unit #026-032

County: Montgomery

Municipality: Whitpain Township

Address: 334 Railroad Avenue

Historic Name/Other Name:

SITE PLAN**PHOTO INFORMATION**

Number	Description of View	Direction of Camera
1	House – façade	
2		
3		
4		
5		
6		
Photographer Name: Robert Wise		Date: 1999
Negative Location: Robert Wise Consulting, Station Square 1, Suite 104, 37 N. Valley Road, Paoli PA 19301		

PENNSYLVANIA HISTORIC RESOURCE SURVEY FORM - DATA SHEET

Pennsylvania Historical and Museum Commission, Bureau for Historic Preservation

89B

IDENTIFICATION AND LOCATION

Survey Code: 098 Tax Parcel/Other No.: 66-00-05830-00-8 Block Unit #026-032

County: 1. Montgomery 091 2.

Municipality: 1. Whitpain Township 2.

Address: 334 Railroad Avenue Historic Name:

Other Name:

Owner Name/Address: William & Janis Lucas 334 Railroad Ave. Ambler PA 19002

Owner Category: Private Public-local Public-state Public-federal

Resource Category: Building District Site Structure Object

Number/Approximate Number of Resources Covered by This Form: 1

USGS Quad: 1. Lansdale 2.

UTM A. _____ C. _____

References: B. _____ D. _____

HISTORIC AND CURRENT FUNCTIONS

Historic Function Category: Subcategory: Code:

A. Residence Dwelling _____

B. _____

C. _____

D. _____

Particular Type: A. _____

B. _____

C. _____

D. _____

Current Function Category: Subcategory: Code:

A. Single Family Residence Dwelling _____

B. _____

C. _____

D. _____

PHYSICAL DESCRIPTION

Architectural Classification: A. Victorian Gothic _____

B. _____

D. _____

Exterior Materials: Foundation _____ Roof _____

Walls stone _____ Walls _____

Other _____ Other _____

Structural System: 1. _____ 2. _____

Width _____ Depth _____ Stories/Height 2.5 _____

HISTORICAL INFORMATION

Year Built: ___ ca. _____ Additions/Alterations Dates: ___ ca. ___ ca. ___
Basis for Dating: Documentary Physical
Explain: Tax records

Cultural/Ethnic Affiliation: 1. _____ 2. _____ Associated Individuals: 1. ____ 2.
Associated Events: 1. _____ 2. _____ Architects/Engineers: 1. ____ 2.
Builders: 1. _____ 2.

MAJOR BIBLIOGRAPHICAL REFERENCES

PREVIOUS SURVEY, DETERMINATIONS

EVALUATION (Survey Director/Consultants Only)

Individual NR Potential: ___ Yes No Context(s): _____
Contributes to Potential District Yes No District Name/Status: _____

Classification: This house is a Class II resource due to architecture and alterations.

THREATS

Threats: 1. None 2. Public Development 3. Private Development 4. Neglect 5. Other

Explain:

SURVEYOR INFORMATION

Surveyor Name/Title: Robert Wise Date: 6/16/2000
Project Name: Whitpain Township Historic Resource Survey
Organization: Robert Wise Consulting/Whitpain Township Telephone: (610) 722-5818
Street and No.: Station Square 1, Suite 104, 37 North Valley Road
City, State: Paoli, Pa Zip Code: 19301
Additional Survey Documentation: n/a
Associated Survey Codes: n/a

PENNSYLVANIA HISTORICAL RESOURCE SURVEY FORM
NARRATIVE SHEET 89C

Pennsylvania Historical and Museum Commission
Bureau for Historic Preservation

Survey Code: 098 Tax Parcel/Other No.: 66-00-05830-00-8 Block Unit #026-032
County: Montgomery 091 Municipality: Whitpain Township
Address: 334 Railroad Avenue
Historic/Other Name:

PHYSICAL DESCRIPTION:

This is a Victorian Gothic-style house built of uncoursed stone. It is a three-bay, two and a half story house. It has one interior end chimney and cross gables. The gables have patterned wood shingles above the second floor and paired windows. The windows are double hung with arched heads matching the arched stonework above them. The centered door has a large rectangular transom and sidelights. Four simple unfluted columns sit on brick bases and support a one-story hipped roof porch on the façade; a decorative corner brace connects the porch to the stonewall. A one-story addition off the back of the house gives it a T-shaped plan. This house is in poor condition.

Classification: This house is a Class II resource due to architecture and alterations.

