

PENNSYLVANIA HISTORIC RESOURCE SURVEY FORM PHOTO/SITE PLAN SHEET

Pennsylvania Historic and Museum Commission

Bureau of Historic Preservation

Box 1026, Harrisburg, PA 17108-1026

Survey Code/Tax Parcel/Other No.: 038 / 66-00-03286-00-5 Block Unit #018-007

County: Montgomery

Municipality: Whitpain Township

Address: 353 Lewis Lane

Historic Name/Other Name:

SITE PLAN

PHOTO INFORMATION



Number	Description of View	Direction of Camera
1	House – façade	
2	House -- rear	
3		
4		
5		
6		
Photographer Name:	Robert Wise	Date: 1999
Negative Location:	Robert Wise Consulting, Station Square 1, Suite 104, 37 N. Valley Road, Paoli PA 19301	

PENNSYLVANIA HISTORIC RESOURCE SURVEY FORM - DATA SHEET

Pennsylvania Historical and Museum Commission, Bureau for Historic Preservation

89B

IDENTIFICATION AND LOCATION

Survey Code: 038 Tax Parcel/Other No.: 66-00-03286-00-5 Block Unit #018-007

County: 1. Montgomery 091 2.

Municipality: 1. Whitpain Township 2.

Address: 353 Lewis Lane Historic Name:

Other Name:

Owner Name/Address: Phoebe Wetzel 353 Lewis Lane Ambler PA 19002

Owner Category: Private Public-local Public-state Public-federal

Resource Category: Building District Site Structure Object

Number/Aproximate Number of Resources Covered by This Form: 2

USGS Quad: 1. Lansdale 2.

UTM A. _____ C. _____

References: B. _____ D. _____

HISTORIC AND CURRENT FUNCTIONS

Historic Function Category: **Subcategory:** **Code:**

A. Residence Dwelling _____

B. _____

C. _____

D. _____

Particular Type: A. _____

B. _____

C. _____

D. _____

Current Function Category: **Subcategory:** **Code:**

A. Single Family Residence Dwelling _____

B. _____

C. _____

D. _____

PHYSICAL DESCRIPTION

Architectural Classification: A. Colonial Revival _____

B. _____

C. _____

Other: _____

Exterior Materials: Foundation _____ Roof _____

Walls stone _____ Walls _____

Other _____ Other _____

Structural System: 1. _____ 2. _____

Width 50 feet _____ Depth _____ Stories/Height 2.5 _____

HISTORICAL INFORMATION

Year Built: ca. 1910 Additions/Alterations Dates: ca. ca.
Basis for Dating: Documentary Physical
Explain: Tax records

Cultural/Ethnic Affiliation: 1. _____ 2. _____ Associated Individuals: 1. _____ 2.
Associated Events: 1. _____ 2. _____ Architects/Engineers: 1. _____ 2.
Builders: 1. _____ 2.

MAJOR BIBLIOGRAPHICAL REFERENCES

PREVIOUS SURVEY, DETERMINATIONS

EVALUATION (Survey Director/Consultants Only)

Individual NR Potential: Yes No Context(s): _____
Contributes to Potential District Yes No District Name/Status: _____

Classification: This house is an excellent example of Colonial Revival architecture and is a Class I resource. It is also located on a large property.

THREATS

Threats: 1. None 2. Public Development 3. Private Development 4. Neglect 5. Other
Explain:

SURVEYOR INFORMATION

Surveyor Name/Title: Robert Wise Date: 6/16/2000
Project Name: Whitpain Township Historic Resource Survey
Organization: Robert Wise Consulting/Whitpain Township Telephone: (610) 722-5818
Street and No.: Station Square 1, Suite 104, 37 North Valley Road
City, State: Paoli, Pa Zip Code: 19301
Additional Survey Documentation: n/a
Associated Survey Codes: n/a

PENNSYLVANIA HISTORICAL RESOURCE SURVEY FORM
NARRATIVE SHEET 89C

Pennsylvania Historical and Museum Commission
Bureau for Historic Preservation

Survey Code: 038 Tax Parcel/Other No.: 66-00-03286-00-5 Block Unit #018-007
County: Montgomery 091 Municipality: Whitpain Township
Address: 353 Lewis Lane
Historic/Other Name:

PHYSICAL DESCRIPTION:

This Colonial Revival house sits perpendicular to Lewis Lane. It is a 2½ story, five bay house with an exterior end chimneys in each gable. The house is composed of semi-coursed stone. Three small gabled roof dormers cut through the roof and have windows with arched sashes. A pent roof divides the façade; the second story windows have shutters, and the first story windows are bands separated by the door. There is an open porch on the left side of the façade resting upon unfluted round columns, while an enclosed porch and greenhouse has been added off the other end of the façade. The rear of the house is surprisingly different. The third dormer is replaced with a large gable. Near the door is a large rounded stair window; most of the windows on the rear of the house are small and cut irregularly into the side of the house. An entry porch rests upon columns and shades the door with its transom and sidelights. To the right of the door is a tripartite window.

Associated Resource: (Garage) A frame garage associated with this house was built c. 1913.
(C)

Classification: This house is an excellent example of Colonial Revival architecture and is a Class I resource. It is also located on a large property.

