

**PENNSYLVANIA HISTORIC RESOURCE SURVEY FORM PHOTO/SITE PLAN SHEET****Pennsylvania Historic and Museum Commission****Bureau of Historic Preservation****Box 1026, Harrisburg, PA 17108-1026**Survey Code/Tax Parcel/Other No.: 046 / 66 00 06169 00 2 Block-Unit #019-023County: MontgomeryMunicipality: Whitpain TownshipAddress: 430 Mallard Circle

Historic Name/Other Name: \_\_\_\_\_

**SITE PLAN****PHOTO INFORMATION**

Number	Description of View	Direction of Camera
1	House	
2	House	
3		
4		
5		
6		
Photographer Name:	Robert Wise	Date: 1999
Negative Location:	Robert Wise Consulting, Station Square 1, Suite 104, 37 N. Valley Road, Paoli PA 19301	

# PENNSYLVANIA HISTORIC RESOURCE SURVEY FORM - DATA SHEET

Pennsylvania Historical and Museum Commission, Bureau for Historic Preservation

89B

## IDENTIFICATION AND LOCATION

Survey Code: 046 Tax Parcel/Other No.: 66 00 06169 00 2 Block Unit #019-023

County: 1. Montgomery 091 2.

Municipality: 1. Whitpain Township 2.

Address: 430 Mallard Circle Historic Name:

Other Name:

Owner Name/Address: John P. & Susan G. Gleason 430 Mallard Circle Blue Bell PA 19422

Owner Category: x Private Public-local Public-state Public-federal

Resource Category: x Building District Site Structure Object

Number/Approximate Number of Resources Covered by This Form: 1

USGS Quad: 1. Lansdale 2.

UTM A. \_\_\_\_\_ C. \_\_\_\_\_

References: B. \_\_\_\_\_ D. \_\_\_\_\_

## HISTORIC AND CURRENT FUNCTIONS

Historic Function Category: Residence Subcategory: Dwelling Code: -----

A. 1800 4,502 SF Land 1.82 Acre -----

B. ----- -----

C. ----- -----

D. ----- -----

Particular Type: A. \_\_\_\_\_

B. \_\_\_\_\_

C. \_\_\_\_\_

D. \_\_\_\_\_

Current Function Category: Single Family Residence Subcategory: Dwelling Code: -----

A. ----- -----

B. ----- -----

C. ----- -----

D. ----- -----

## PHYSICAL DESCRIPTION

Architectural Classification: A. Folk Victorian -----

B. ----- -----

D. ----- -----

Exterior Materials: Foundation ----- Roof -----

Walls ----- stucco ----- Walls -----

Other ----- Other -----

Structural System: 1. ----- 2. -----

Width ----- Depth ----- Stories/Height 2.5

## HISTORICAL INFORMATION

Year Built: ca. 1800 Additions/Alterations Dates: ca. ca.  
Basis for Dating: x Documentary Physical  
Explain: Tax records

Cultural/Ethnic Affiliation: 1. \_\_\_\_\_ 2. \_\_\_\_\_ Associated Individuals: 1. \_\_\_\_\_ 2.  
Associated Events: 1. \_\_\_\_\_ 2. \_\_\_\_\_ Architects/Engineers: 1. \_\_\_\_\_ 2.  
Builders: 1. \_\_\_\_\_ 2.

## MAJOR BIBLIOGRAPHICAL REFERENCES

## PREVIOUS SURVEY, DETERMINATIONS

## EVALUATION (Survey Director/Consultants Only)

Individual NR Potential: Yes x No Context(s): \_\_\_\_\_  
Contributes to Potential District Yes    No District Name/Status: \_\_\_\_\_

**Classification:** Due to an abundance of large additions, the house is Class II.

## THREATS

Threats: x 1. None 2. Public Development 3. Private Development 4. Neglect 5. Other

Explain:

## SURVEYOR INFORMATION

Surveyor Name/Title: Robert Wise Date: 6/16/2000  
Project Name: Whitpain Township Historic Resource Survey  
Organization: Robert Wise Consulting/Whitpain Township Telephone: (610) 722-5818  
Street and No.: Station Square 1, Suite 104, 37 North Valley Road  
City, State: Paoli, Pa Zip Code: 19301  
Additional Survey Documentation: n/a  
Associated Survey Codes: n/a

PENNSYLVANIA HISTORICAL RESOURCE SURVEY FORM  
NARRATIVE SHEET 89C

Pennsylvania Historical and Museum Commission  
Bureau for Historic Preservation

Survey Code: 046 Tax Parcel/Other No.: 66 00 06169 00 2 Block-Unit #019-023

County: Montgomery 091 Municipality: Whitpain Township

Address: 430 Mallard Circle

Historic/Other Name:

**PHYSICAL DESCRIPTION:**

Constructed c. 1800, this Folk Victorian-style house has several additions including an enclosed front porch. The core is an el-shaped building with 2.5 stories, a cross gabled, asphalt shingled roof, and stucco walls. There are at least two additions, including a nearly identical cross-gabled section on the rear and a 1.5 story extension off the rear gabled addition. The building, with additions, is also el-shaped and forms two sides of a courtyard, a stucco covered wall forming the remaining sides. The additions are clad in asphalt and have asphalt shingled roofs. Other details include weatherboard-clad gabled dormers on the core and smaller gabled dormers on the extension. Windows are double hung sash, several of which are paired. The front or side porch is a shed-roofed unit with a stucco base, glass paneled walls, and three light transoms. The house is in excellent condition.

**Classification:** Due to an abundance of large additions, the house is Class II.

