

PENNSYLVANIA HISTORIC RESOURCE SURVEY FORM PHOTO/SITE PLAN SHEET

Pennsylvania Historic and Museum Commission

Bureau of Historic Preservation

Box 1026, Harrisburg, PA 17108-1026


Survey Code/Tax Parcel/Other No.: 010 / 66 00 00847 00 5 Block-Unit #011B-036

County: Montgomery

Municipality: Whitpain Township

Address: 482 Cathcart Road

Historic Name/Other Name:

SITE PLAN**PHOTO INFORMATION**

Number	Description of View	Direction of Camera
1	House – façade	
2	House – façade (right)	
3	Corn Crib	
4		
5		
6		
Photographer Name: Robert Wise		Date: 1999
Negative Location: Robert Wise Consulting, Station Square 1, Suite 104, 37 N. Valley Road, Paoli PA 19301		

PENNSYLVANIA HISTORIC RESOURCE SURVEY FORM - DATA SHEET

Pennsylvania Historical and Museum Commission, Bureau for Historic Preservation

89B

IDENTIFICATION AND LOCATION

Survey Code: 010 Tax Parcel/Other No.: 66 00 00847 00 5 Block Unit #011B-036

County: 1. Montgomery 091 2.

Municipality: 1. Whitpain Township 2.

Address: 482 Cathcart Road Historic Name:

Other Name:

Owner Name/Address: G. Richard & Ural R. Reehling 482 Cathcart Road, Blue Bell PA 19422

Owner Category: Private Public-local Public-state Public-federal

Resource Category: Building District Site Structure Object

Number/Approximate Number of Resources Covered by This Form: 5

USGS Quad: 1. Lansdale 2.

UTM A. _____ C. _____

References: B. _____ D. _____

HISTORIC AND CURRENT FUNCTIONS

Historic Function Category: Subcategory: Code:

A. Residence 1880 2,701 SF Land 1.03 Acre Dwelling _____

B. _____

C. _____

D. _____

Particular Type: A. _____

B. _____

C. _____

D. _____

Current Function Category: Subcategory: Code:

A. Single Family Residence Dwelling _____

B. _____

C. _____

D. _____

PHYSICAL DESCRIPTION

Architectural Classification:

B. _____

D. _____

Exterior Materials: Foundation _____

A. vernacular _____

C. _____

Other: _____

Walls stucco _____

Roof asphalt shingles _____

Walls _____

Other _____

Other _____

Structural System: 1. _____ 2. _____

Width 3 bay _____ Depth _____ Stories/Height 3 _____

HISTORICAL INFORMATION

Year Built: ca. 1880 Additions/Alterations Dates: ca. ca.
Basis for Dating: x Documentary Physical
Explain: Tax records

Cultural/Ethnic Affiliation: 1. _____ 2. _____ Associated Individuals: 1. _____ 2.
Associated Events: 1. _____ 2. _____ Architects/Engineers: 1. _____ 2.
Builders: 1. _____ 2.

MAJOR BIBLIOGRAPHICAL REFERENCES

PREVIOUS SURVEY, DETERMINATIONS

EVALUATION (Survey Director/Consultants Only)

Individual NR Potential: Yes x No Context(s): _____
Contributes to Potential District Yes No District Name/Status: _____

Classification: The many alterations on this house make it a Class II resource.

THREATS

Threats: x 1. None 2. Public Development 3. Private Development 4. Neglect 5. Other

Explain:

SURVEYOR INFORMATION

Surveyor Name/Title: Robert Wise Date: 6/16/2000
Project Name: Whitpain Township Historic Resource Survey
Organization: Robert Wise Consulting/Whitpain Township Telephone: (610) 722-5818
Street and No.: Station Square 1, Suite 104, 37 North Valley Road
City, State: Paoli, Pa Zip Code: 19301
Additional Survey Documentation: n/a
Associated Survey Codes: n/a

PENNSYLVANIA HISTORICAL RESOURCE SURVEY FORM
NARRATIVE SHEET 89C

Pennsylvania Historical and Museum Commission
Bureau for Historic Preservation

Survey Code: 010 Tax Parcel/Other No.: 66 00 00847 00 5 Block-Unit #011B-036
County: Montgomery 091 Municipality: Whitpain Township
Address: 482 Cathcart Road
Historic/Other Name:

PHYSICAL DESCRIPTION:

This house is an example of vernacular construction. It was once the farmstead for a large farm, now developed. It is a three story, three bay house measuring 20 x 35 feet and having interior end chimneys in the gable ends. The house was built with brick c. 1880 and covered with stucco. Each window has louvered shutters; two large 20th century bay windows appear on the first floor. A pent roof separates the first floor from the second and has a gabled entry hood supported by square columns. A one story shed addition appears on the rear of the house supported by square columns.

Additional Resource: (1) **Double Corn Crib** The walls of this building slope outward to give the building more volume. It is an end gabled, 1½ story frame building.

Classification: The many alterations on this house make it a Class II resource.



