

PENNSYLVANIA HISTORIC RESOURCE SURVEY FORM PHOTO/SITE PLAN SHEET

Pennsylvania Historic and Museum Commission

Bureau of Historic Preservation

Box 1026, Harrisburg, PA 17108-1026

Survey Code/Tax Parcel/Other No.: 041 / 66 00 03277 01 4 Block Unit #018-091

County: Montgomery


Municipality: Whitpain Township

Address: 555 Lewis Lane

Historic Name/Other Name: _____

SITE PLAN

PHOTO INFORMATION



Number	Description of View	Direction of Camera
1	Carriage House	
2	Barn	
3	Barn	
4	Open Shed	
5	Barn and Corn Crib	
6		
Photographer Name: Robert Wise		Date: 1999
Negative Location: Robert Wise Consulting, Station Square 1, Suite 104, 37 N. Valley Road, Paoli PA 19301		

PENNSYLVANIA HISTORIC RESOURCE SURVEY FORM - DATA SHEET

Pennsylvania Historical and Museum Commission, Bureau for Historic Preservation

89B

IDENTIFICATION AND LOCATION

Survey Code: 041 Tax Parcel/Other No.: 66 00 03277 01 4 Block Unit #018-091

County: 1. Montgomery 091 2. _____

Municipality: 1. Whitpain Township 2. _____

Address: 555 Lewis Lane Historic Name: _____

Other Name: _____

Owner Name/Address: Francis J. Cary 485 Lewis Lane Ambler PA 19002

Owner Category: x Private _____ Public-local _____ Public-state _____ Public-federal

Resource Category: x Building _____ District _____ Site _____ Structure _____ Object

Number/Approximate Number of Resources Covered by This Form: 5

USGS Quad: 1. Lansdale 2. _____

UTM A. _____ C. _____

References: B. _____ D. _____

HISTORIC AND CURRENT FUNCTIONS

Historic Function Category: _____ Subcategory: _____ Code: _____

A. Residence _____ Dwelling _____

B. _____

C. _____

D. _____

Particular Type: A. _____

B. _____

C. _____

D. _____

Current Function Category: _____ Subcategory: _____ Code: _____

A. Single Family Residence _____ Dwelling _____

B. _____

C. _____

D. _____

PHYSICAL DESCRIPTION

Architectural Classification:

B. _____ A. _____

C. _____

D. _____ Other: _____

Exterior Materials: Foundation _____ Roof _____

Walls stucco _____ Walls _____

Other _____ Other _____

Structural System: 1. _____ 2. _____

Width _____ Depth _____ Stories/Height 1 _____

HISTORICAL INFORMATION

Year Built: ____ ca. ____ Additions/Alterations Dates: ____ ca. ____ ca. ____

Basis for Dating: ☒ Documentary ☐ Physical

Explain: Tax records

Cultural/Ethnic Affiliation: 1. _____ 2. _____ Associated Individuals: 1. _____ 2. _____
Associated Events: 1. _____ 2. _____ Architects/Engineers: 1. _____ 2. _____
Builders: 1. _____ 2. _____

MAJOR BIBLIOGRAPHICAL REFERENCES

PREVIOUS SURVEY, DETERMINATIONS

EVALUATION (Survey Director/Consultants Only)

Individual NR Potential: ☒ Yes ☐ No Context(s): _____

Contributes to Potential District ☐ Yes ☐ No District Name/Status: _____

Classification: These buildings are associated with 525 Lewis Lane, which is a Class I resource. As a unit (555 Lewis Lane only), they also constitute a Class I resource and are on the National Register with 525 Lewis Lane.

THREATS

Threats: ☒ 1. None 2. Public Development 3. Private Development 4. Neglect 5. Other

Explain:

SURVEYOR INFORMATION

Surveyor Name/Title: Robert Wise Date: 6/16/2000

Project Name: Whitpain Township Historic Resource Survey

Organization: Robert Wise Consulting/Whitpain Township Telephone: (610) 722-5818

Street and No.: Station Square 1, Suite 104, 37 North Valley Road

City, State: Paoli, Pa Zip Code: 19301

Additional Survey Documentation: n/a

Associated Survey Codes: n/a

PENNSYLVANIA HISTORICAL RESOURCE SURVEY FORM
NARRATIVE SHEET 89C

Pennsylvania Historical and Museum Commission
Bureau for Historic Preservation

Survey Code: 041 Tax Parcel/Other No.: 66 00 03277 01 4 Block-Unit #018-091
County: Montgomery 091 Municipality: Whitpain Township
Address: 555 Lewis Lane
Historic/Other Name:

PHYSICAL DESCRIPTION:

This is the location of a group of resources associated with 485 & 525 Lewis Lane.

- (1) **Carriage House.** This stucco covered building is a one story building with a hipped roof and a centered cross gable. There are two large sliding doors on the front of the building and small windows. (C)
- (2) **Barn.** Built of uncoursed stone, this barn is in excellent condition. It is an end-gabled structure with few windows. (C)
- (3) **Open Shed.** This structure has a stone foundation covered with stucco and a frame upper story. The shed has three walls and is open on the fourth side. (C)
- (4) **Frame Barn.** This building stands on stone piers and is clad with vertical wood siding. It has sliding doors and a frame shed addition. A single window is located in the gable (C).
- (5) **Corn crib.** This building follows the pattern of many corncribs in Whitpain township with its flared walls and end gable construction. (C)

Classification: These buildings are associated with 485 & 525 Lewis Lane, which is a Class I resource. As a unit (555 Lewis Lane only), they also constitute a Class I resource and are on the National Register with 525 Lewis Lane.





