

PENNSYLVANIA HISTORIC RESOURCE SURVEY FORM PHOTO/SITE PLAN SHEET

Pennsylvania Historic and Museum Commission
 Bureau of Historic Preservation
 Box 1026, Harrisburg, PA 17108-1026

Survey Code/Tax Parcel/Other No.: 043 / 66 00 03277 00 5 Block-Unit #018-043

County: Montgomery

Municipality: Whitpain Township

Address: 585 Lewis Lane

Historic Name/Other Name:

SITE PLAN

PHOTO INFORMATION



Number	Description of View	Direction of Camera
1	House – façade	
2	House – rear	
3		
4		
5		
6		
Photographer Name: Robert Wise		Date: 1999
Negative Location: Robert Wise Consulting, Station Square 1, Suite 104, 37 N. Valley Road, Paoli PA 19301		

PENNSYLVANIA HISTORIC RESOURCE SURVEY FORM - DATA SHEET

Pennsylvania Historical and Museum Commission, Bureau for Historic Preservation

89B

IDENTIFICATION AND LOCATION

Survey Code: 043 Tax Parcel/Other No.: 66 00 03277 00 5 Block Unit #018-043

County: 1. Montgomery 091 2.

Municipality: 1. Whitpain Township 2.

Address: 585 Lewis Lane Historic Name:

Other Name:

Owner Name/Address: Ronald C. Anderson P.O. Box 390 Ambler PA 19002

Owner Category: Private Public-local Public-state Public-federal

Resource Category: Building District Site Structure Object

Number/Approximate Number of Resources Covered by This Form: 1

USGS Quad: 1. Lansdale 2.

UTM A. _____ C. _____

References: B. _____ D. _____

HISTORIC AND CURRENT FUNCTIONS

Historic Function Category: **Subcategory:** **Code:**

A. Residence 1801 3,933 SF Dwelling _____

B. _____

C. _____

D. _____

Particular Type: A. _____

B. _____

C. _____

D. _____

Current Function Category: **Subcategory:** **Code:**

A. Single Family Residence Dwelling _____

B. _____

C. _____

D. _____

PHYSICAL DESCRIPTION

Architectural Classification: A. Georgian _____

B. _____

D. _____

Exterior Materials: Foundation _____

Roof _____

Walls stucco _____

Walls _____

Other _____

Other _____

Structural System: 1. _____

2. _____

Width 5 bay _____ Depth _____ Stories/Height 2 _____

HISTORICAL INFORMATION

Year Built: ca. 1801 Additions/Alterations Dates: ca. ca.
Basis for Dating: x Documentary Physical
Explain: Tax records

Cultural/Ethnic Affiliation: 1. _____ 2. _____ Associated Individuals: 1. _____ 2.
Associated Events: 1. _____ 2. _____ Architects/Engineers: 1. _____ 2.
Builders: 1. _____ 2.

MAJOR BIBLIOGRAPHICAL REFERENCES

PREVIOUS SURVEY, DETERMINATIONS

EVALUATION (Survey Director/Consultants Only)

Individual NR Potential: Yes x No Context(s): _____
Contributes to Potential District Yes No District Name/Status: _____

Classification: The many rear additions make this house a Class II resource.

THREATS

Threats: x 1. None 2. Public Development 3. Private Development 4. Neglect 5. Other

Explain:

SURVEYOR INFORMATION

Surveyor Name/Title: Robert Wise Date: 6/16/2000
Project Name: Whitpain Township Historic Resource Survey
Organization: Robert Wise Consulting/Whitpain Township Telephone: (610) 722-5818
Street and No.: Station Square 1, Suite 104, 37 North Valley Road
City, State: Paoli, Pa Zip Code: 19301
Additional Survey Documentation: n/a
Associated Survey Codes: n/a

PENNSYLVANIA HISTORICAL RESOURCE SURVEY FORM
NARRATIVE SHEET 89C

Pennsylvania Historical and Museum Commission
Bureau for Historic Preservation

Survey Code: 043 Tax Parcel/Other No.: 66 00 03277 00 5 Block-Unit #018-043

County: Montgomery 091 Municipality: Whitpain Township

Address: 585 Lewis Lane

Historic/Other Name:

PHYSICAL DESCRIPTION:

This house is an example of Georgian architecture with several additions. The core is a two story, three bay house with an interior end chimney in one of the gable ends and a small semicircular window in the other. The house, built c. 1801, is clad with stucco. Centered in the middle of the façade, a roof dormer with a gabled roof brings some symmetry to the house. The door is in the first bay and has sidelights and a transom. All windows have shutters. A two story addition to the side of the core is a two bay structure with an exterior end chimney. This addition is also clad in stucco and follows the pattern of windows and the simple cornice of the core. A two story addition off the rear of the core is clad in stucco and has a similar roof dormer and windows as the core. The next rear addition is a frame one story element which leads to a frame two story addition farther back. These last two additions are gabled additions sitting perpendicular to the core.

Classification: The many rear additions make this house a Class II resource.

