

PENNSYLVANIA HISTORIC RESOURCE SURVEY FORM PHOTO/SITE PLAN SHEET

Pennsylvania Historic and Museum Commission

Bureau of Historic Preservation

Box 1026, Harrisburg, PA 17108-1026

Survey Code/Tax Parcel/Other No.: 044 / 66 00 03271 00 2 Block-Unit #018-066

County: Montgomery

Municipality: Whitpain Township

Address: 675 Lewis Lane

Historic Name/Other Name:

SITE PLAN

PHOTO INFORMATION



Number	Description of View	Direction of Camera
1	House – core	
2	House – addition	
3		
4		
5		
6		
Photographer Name:	Robert Wise	Date: 1999
Negative Location:	Robert Wise Consulting, Station Square 1, Suite 104, 37 N. Valley Road, Paoli PA 19301	

PENNSYLVANIA HISTORIC RESOURCE SURVEY FORM - DATA SHEET

Pennsylvania Historical and Museum Commission, Bureau for Historic Preservation

89B

IDENTIFICATION AND LOCATION

Survey Code: 044 Tax Parcel/Other No.: 66 00 03271 00 2 Block Unit #018-066

County: 1. Montgomery 091 2.

Municipality: 1. Whitpain Township 2.

Address: 675 Lewis Lane Historic Name:

Other Name:

Owner Name/Address: Ross L. & Marcia W. Campbell 675 Lewis Lane Ambler PA 19002

Owner Category: Private Public-local Public-state Public-federal

Resource Category: Building District Site Structure Object

Number/Approximate Number of Resources Covered by This Form: 2

USGS Quad: 1. Lansdale 2.

UTM A. _____ C. _____

References: B. _____ D. _____

HISTORIC AND CURRENT FUNCTIONS

Historic Function Category: **Subcategory:** **Code:**

A. Residence 1819 3,159 SF Dwelling _____

B. _____

C. _____

D. _____

Particular Type: A. _____

B. _____

C. _____

D. _____

Current Function Category: **Subcategory:** **Code:**

A. Single Family Residence Dwelling _____

B. _____

C. _____

D. _____

PHYSICAL DESCRIPTION

Architectural Classification: A. Penn Plan _____

B. _____

D. _____

C. _____

Other: _____

Exterior Materials: Foundation _____ Roof _____ slate _____

Walls brick _____ Walls _____

Other _____ Other _____

Structural System: 1. _____ 2. _____

Width _____ Depth _____ Stories/Height 2.5 _____

HISTORICAL INFORMATION

Year Built: ca. 1819 Additions/Alterations Dates: ca. ca.
Basis for Dating: x Documentary Physical
Explain: Tax records

Cultural/Ethnic Affiliation: 1. _____ 2. _____ Associated Individuals: 1. _____ 2.
Associated Events: 1. _____ 2. _____ Architects/Engineers: 1. _____ 2.
Builders: 1. _____ 2.

MAJOR BIBLIOGRAPHICAL REFERENCES

PREVIOUS SURVEY, DETERMINATIONS

EVALUATION (Survey Director/Consultants Only)

Individual NR Potential: Yes x No Context(s): _____
Contributes to Potential District Yes No District Name/Status:

Classification: The alterations on this house make it a Class II resource.

THREATS

Threats: x 1. None 2. Public Development 3. Private Development 4. Neglect 5. Other

Explain:

SURVEYOR INFORMATION

Surveyor Name/Title: Robert Wise Date: 6/16/2000
Project Name: Whitpain Township Historic Resource Survey
Organization: Robert Wise Consulting/Whitpain Township Telephone: (610) 722-5818
Street and No.: Station Square 1, Suite 104, 37 North Valley Road
City, State: Paoli, Pa Zip Code: 19301
Additional Survey Documentation: n/a
Associated Survey Codes: n/a

PENNSYLVANIA HISTORICAL RESOURCE SURVEY FORM
NARRATIVE SHEET 89C

Pennsylvania Historical and Museum Commission
Bureau for Historic Preservation

Survey Code: 044 Tax Parcel/Other No.: 66 00 03271 00 2 Block-Unit #018-066
County: Montgomery 091 Municipality: Whitpain Township
Address: 675 Lewis Lane
Historic/Other Name:

PHYSICAL DESCRIPTION:

This house is an example of the Penn Plan construction. The core constructed of brick c. 1819 is a 2½-story building with a three bays core. The core has an interior end chimney and a small Palladian window in the gable end. There are two gabled roof dormers and a large one-story entry porch resting upon square columns. An addition to the house c. 1933 is clad in stucco. This addition is a 2½ story, two bay element with a cantilevered balcony decorated with an iron railing. A large bay window on the first floor breaks through the gable end of the addition. Many of the windows on the addition are paired. There is also a one-story addition on the rear of the house with a small chimney.

Classification: The alterations on this house make it a Class II resource.

