

PENNSYLVANIA HISTORIC RESOURCE SURVEY FORM PHOTO/SITE PLAN SHEET

Pennsylvania Historic and Museum Commission

Bureau of Historic Preservation

Box 1026, Harrisburg, PA 17108-1026

Survey Code/Tax Parcel/Other No.: 004 / 66 00 00685 00 5 Block-Unit #023D-072

County: Montgomery


Municipality: Whitpain Township

Address: 701 Butler Pike

Historic Name/Other Name:

SITE PLAN

PHOTO INFORMATION



Number	Description of View	Direction of Camera
1	House – façade	
2	Barn	
3		
4		
5		
6		
Photographer Name:	Robert Wise	Date: 1999
Negative Location:	Robert Wise Consulting, Station Square 1, Suite 104, 37 N. Valley Road, Paoli PA 19301	

PENNSYLVANIA HISTORIC RESOURCE SURVEY FORM - DATA SHEET

Pennsylvania Historical and Museum Commission, Bureau for Historic Preservation

89B

IDENTIFICATION AND LOCATION

Survey Code: 004 Tax Parcel/Other No.: 66 00 00685 00 5 Block Unit #023D-072

County: 1. Montgomery 091 2.

Municipality: 1. Whitpain Township 2.

Address: 701 Butler Pike Historic Name:

Other Name:

Owner Name/Address: James M. and Jolly W. Stewart 701 Butler Pike Ambler PA 19002

Owner Category: Private Public-local Public-state Public-federal

Resource Category: Building District Site Structure Object

Number/Approximate Number of Resources Covered by This Form: 2

USGS Quad: 1. Lansdale 2.

UTM A. _____ C. _____

References: B. _____ D. _____

HISTORIC AND CURRENT FUNCTIONS

Historic Function Category:

A. Residence 1700 5,380 SF Land 3.10 acre Subcategory: Dwelling _____ Code: _____

B. _____

C. _____

D. _____

Particular Type:

A. _____

B. _____

C. _____

D. _____

Current Function Category:

A. Single Family Residence Dwelling _____

B. _____

C. _____

D. _____

PHYSICAL DESCRIPTION

Architectural Classification:

A. Dutch Colonial Revival _____

B. _____

D. _____

C. _____

Other: _____

Exterior Materials:

Foundation _____

Roof wood shingle _____

Walls stucco _____

Walls _____

Other _____

Other _____

Structural System:

1. _____ 2. _____

Width _____ Depth _____ Stories/Height 2 _____

HISTORICAL INFORMATION

Year Built: ca. 1700 Additions/Alterations Dates: ca. ca.
Basis for Dating: x Documentary Physical
Explain: Tax records

Cultural/Ethnic Affiliation: 1. _____ 2. _____ Associated Individuals: 1. _____ 2.
Associated Events: 1. _____ 2. _____ Architects/Engineers: 1. _____ 2.
Builders: 1. _____ 2.

MAJOR BIBLIOGRAPHICAL REFERENCES

PREVIOUS SURVEY, DETERMINATIONS

EVALUATION (Survey Director/Consultants Only)

Individual NR Potential: Yes x No Context(s): _____
Contributes to Potential District Yes No District Name/Status: _____

Classification: This house has undergone many alterations in its history that make it a Class II resource.

THREATS

Threats: x 1. None 2. Public Development 3. Private Development 4. Neglect 5. Other

Explain:

SURVEYOR INFORMATION

Surveyor Name/Title: Robert Wise Date: 6/16/2000
Project Name: Whitpain Township Historic Resource Survey
Organization: Robert Wise Consulting/Whitpain Township Telephone: (610) 722-5818
Street and No.: Station Square 1, Suite 104, 37 North Valley Road
City, State: Paoli, Pa Zip Code: 19301
Additional Survey Documentation: n/a
Associated Survey Codes: n/a

PENNSYLVANIA HISTORICAL RESOURCE SURVEY FORM
NARRATIVE SHEET 89C

Pennsylvania Historical and Museum Commission
Bureau for Historic Preservation

Survey Code: 004 Tax Parcel/Other No.: 66 00 00685 00 5 Block-Unit #023D-072

County: Montgomery 091 Municipality: Whitpain Township

Address: 711 Boehms Church Road

Historic/Other Name:

PHYSICAL DESCRIPTION:

This house is an example of a Colonial house with a flared gambrel roof. Originally built c. 1700, the core is a two-story house 40 ft. long and is covered with stucco. The roof is covered with wood shingles, and it has a molded cornice. A small dormer appears on the front façade. The house has exterior end chimneys. Windows are double sash and have shutters. There have been several additions on the rear of the house. A two-story addition with a flat roof immediately behind the core has a hipped side entrance porch resting on round, smooth columns. Another addition on the rear of the house has a gabled roof and is also two stories tall. The house is in excellent condition.

Associated building. A large carriage shed behind the house is a large two story, end gable building with a wood shingle roof and a square cupola. A one-story addition to this building has board and batten siding and three car bays.

Classification: This house has undergone many alterations in its history that make it a Class II resource.

