

PENNSYLVANIA HISTORIC RESOURCE SURVEY FORM PHOTO/SITE PLAN SHEET

Pennsylvania Historic and Museum Commission
Bureau of Historic Preservation
Box 1026, Harrisburg, PA 17108-1026

Survey Code/Tax Parcel/Other No.: 018 / 66-00-01639-00-5 Block Unit #009-048

County: Montgomery

Municipality: Whitpain Township

Address: 825 DeKalb Pike

Historic Name/Other Name: _____

SITE PLAN**PHOTO INFORMATION**

Number	Description of View	Direction of Camera
1	House – façade	
2		
3		
4		
5		
6		
Photographer Name: Robert Wise		Date: 1999
Negative Location: Robert Wise Consulting, Station Square 1, Suite 104, 37 N. Valley Road, Paoli PA 19301		

PENNSYLVANIA HISTORIC RESOURCE SURVEY FORM - DATA SHEET

Pennsylvania Historical and Museum Commission, Bureau for Historic Preservation

89B

IDENTIFICATION AND LOCATION

Survey Code: 018 Tax Parcel/Other No.: 66-00-01639-00-5 Block Unit #009-048

County: 1. Montgomery 091 2.

Municipality: 1. Whitpain Township 2.

Address: 825 DeKalb Pike Historic Name:

Other Name:

Owner Name/Address: David & Elmer Swartley 825 DeKalb Pike, Center Square PA 19422

Owner Category: Private Public-local Public-state Public-federal

Resource Category: Building District Site Structure Object

Number/Approximate Number of Resources Covered by This Form: 1

USGS Quad: 1. Lansdale 2.

UTM A. _____ C. _____

References: B. _____ D. _____

HISTORIC AND CURRENT FUNCTIONS

Historic Function Category: **Subcategory:** **Code:**

A. Residence Dwelling _____

B. _____

C. _____

D. _____

Particular Type: A. _____

B. _____

C. _____

D. _____

Current Function Category: **Subcategory:** **Code:**

A. Single Family Residence Dwelling _____

B. _____

C. _____

D. _____

PHYSICAL DESCRIPTION

Architectural Classification: A. Gothic _____

B. _____

D. _____

Exterior Materials: Foundation _____ Roof _____

Walls shingles _____ Walls _____

Other _____ Other _____

Structural System: 1. _____ 2. _____

Width 3 bays 28 feet _____ Depth 30 feet _____ Stories/Height 2.5 _____

HISTORICAL INFORMATION

Year Built: ca. 1860 Additions/Alterations Dates: ca. ca.
Basis for Dating: Documentary Physical
Explain: Tax records

Cultural/Ethnic Affiliation: 1. _____ 2. _____ Associated Individuals: 1. _____ 2.
Associated Events: 1. _____ 2. _____ Architects/Engineers: 1. _____ 2.
Builders: 1. _____ 2.

MAJOR BIBLIOGRAPHICAL REFERENCES

PREVIOUS SURVEY, DETERMINATIONS

EVALUATION (Survey Director/Consultants Only)

Individual NR Potential: Yes No Context(s): _____
Contributes to Potential District Yes No District Name/Status:

Classification: Due to alterations the house is Class II.

THREATS

Threats: 1. None 2. Public Development 3. Private Development 4. Neglect 5. Other

Explain:

SURVEYOR INFORMATION

Surveyor Name/Title: Robert Wise Date: 6/16/2000
Project Name: Whitpain Township Historic Resource Survey
Organization: Robert Wise Consulting/Whitpain Township Telephone: (610) 722-5818
Street and No.: Station Square 1, Suite 104, 37 North Valley Road
City, State: Paoli, Pa Zip Code: 19301
Additional Survey Documentation: n/a
Associated Survey Codes: n/a

PENNSYLVANIA HISTORICAL RESOURCE SURVEY FORM
NARRATIVE SHEET 89C

Pennsylvania Historical and Museum Commission
Bureau for Historic Preservation

Survey Code: 018 Tax Parcel/Other No.: 66-00-01639-00-5 Block Unit #009-048

County: Montgomery 091 Municipality: Whitpain Township

Address: 825 DeKalb Pike

Historic/Other Name:

PHYSICAL DESCRIPTION:

This is a 2.5-story, center gabled house designed in the Victorian Gothic mode (c. 1860). It has a cross-gabled, asphalt-shingled roof and is clad in wood shingles. The main façade is three bays wide. It is an ell-shaped core with an infill addition, a small shed-roofed addition attached to the rear and a hipped-roof front porch. Windows are 2 x 2 sash with French doors in the center. The window under the center dormer is pointed. Cornice is molded wood. There is a brick chimney on the right side of house with an awkward swale. The brick is partially covered with stucco. The building measures approximately 30'x30', including additions.

Classification: Due to alterations the house is Class II.

