

PENNSYLVANIA HISTORIC RESOURCE SURVEY FORM PHOTO/SITE PLAN SHEET

Pennsylvania Historic and Museum Commission

Bureau of Historic Preservation

Box 1026, Harrisburg, PA 17108-1026

Survey Code/Tax Parcel/Other No.: 192 / 66 00 06064 00 8 Block-Unit #009-027

County: Montgomery


Municipality: Whitpain Township

Address: 843 Second Avenue

Historic Name/Other Name: _____

SITE PLAN

PHOTO INFORMATION



Number	Description of View	Direction of Camera
1	House – façade	
2	House – façade	
3		
4		
5		
6		
Photographer Name: Robert Wise		Date: 1999

Negative Location: Robert Wise Consulting, Station Square 1, Suite 104,
37 N. Valley Road, Paoli PA 19301

PENNSYLVANIA HISTORIC RESOURCE SURVEY FORM - DATA SHEET

Pennsylvania Historical and Museum Commission, Bureau for Historic Preservation

89B

IDENTIFICATION AND LOCATION

Survey Code: 192 Tax Parcel/Other No.: 66 00 06064 00 8 Block Unit #009-027

County: 1. Montgomery 091 2. _____

Municipality: 1. Whitpain Township 2. _____

Address: 843 Second Avenue Historic Name: _____

Other Name: _____

Owner Name/Address: Robert & Marion Beideman Trustee 843 Second Ave. Center Square PA 19422

Owner Category: ☒ Private ☐ Public-local ☐ Public-state ☐ Public-federal

Resource Category: ☒ Building ☐ District ☐ Site ☐ Structure ☐ Object

Number/Approximate Number of Resources Covered by This Form: 1

USGS Quad: 1. Lansdale 2. _____

UTM A. _____ C. _____

References: B. _____ D. _____

HISTORIC AND CURRENT FUNCTIONS

Historic Function Category: _____ Subcategory: _____ Code: _____

A. Residence Dwelling _____

B. _____

C. _____

D. _____

Particular Type: A. _____

B. _____

C. _____

D. _____

Current Function Category: _____ Subcategory: _____ Code: _____

A. Single Family Residence Dwelling _____

B. _____

C. _____

D. _____

PHYSICAL DESCRIPTION

Architectural Classification:

B. _____

D. _____

A. Ranch _____

C. _____

Other: _____

Exterior Materials: Foundation _____

Walls stucco _____

Other _____

Roof asphalt shingles _____

Walls _____

Other _____

Structural System: 1. _____ 2. _____

Width _____ Depth _____ Stories/Height 1 _____

HISTORICAL INFORMATION

Year Built: ca. Additions/Alterations Dates: ca. ca.
Basis for Dating: x Documentary Physical
Explain: Tax records

Cultural/Ethnic Affiliation: 1. 2. Associated Individuals: 1. 2.
Associated Events: 1. 2. Architects/Engineers: 1. 2.
Builders: 1. 2.

MAJOR BIBLIOGRAPHICAL REFERENCES

PREVIOUS SURVEY, DETERMINATIONS

EVALUATION (Survey Director/Consultants Only)

Individual NR Potential: x Yes No Context(s):
Contributes to Potential District x Yes No District Name/Status: Center Square HD #413

Classification: This house is in the Center Square Historic District.

THREATS

Threats: x 1. None 2. Public Development 3. Private Development 4. Neglect 5. Other

Explain:

SURVEYOR INFORMATION

Surveyor Name/Title: Robert Wise Date: 6/16/2000
Project Name: Whitpain Township Historic Resource Survey
Organization: Robert Wise Consulting/Whitpain Township Telephone: (610) 722-5818
Street and No.: Station Square 1, Suite 104, 37 North Valley Road
City, State: Paoli, Pa Zip Code: 19301
Additional Survey Documentation: n/a
Associated Survey Codes: n/a

PENNSYLVANIA HISTORICAL RESOURCE SURVEY FORM
NARRATIVE SHEET 89C

Pennsylvania Historical and Museum Commission
Bureau for Historic Preservation

Survey Code: 192 Tax Parcel/Other No.: 66 00 06061 00 2 Block-Unit #009-056
County: Montgomery 091 Municipality: Whitpain Township
Address: 843 Second Avenue
Historic/Other Name:

PHYSICAL DESCRIPTION:

This house is an example of the Ranch style, which was a dominant style of the twentieth century. The house is one story and clad with stucco. The ell extension incorporates the two-car garage into the house. A low-pitch roof is clad with asphalt shingles and has gable ends. The main part of the house has two double windows with six over six lights and small shutters. The entry door is on the ell near the junction of the two parts of the ell; it has a sidelight on the left side. A double window between the door and the garage doors repeats the profile of the windows on the main portion of the house.

Classification: This house is in the Center Square Historic District.



