

PENNSYLVANIA HISTORIC RESOURCE SURVEY FORM PHOTO/SITE PLAN SHEET

Pennsylvania Historic and Museum Commission

Bureau of Historic Preservation

Box 1026, Harrisburg, PA 17108-1026

Survey Code/Tax Parcel/Other No.: 021 / 66-00-01789-00-8 Block Unit #005-003

County: Montgomery


Municipality: Whitpain Township

Address: 938 DeKalb Pike

Historic Name/Other Name: _____

SITE PLAN

PHOTO INFORMATION



Number	Description of View	Direction of Camera
1	House – façade	
2	House – façade	
3	House – rear	
4		
5		
6		
Photographer Name:	Robert Wise	Date: 1999

Negative Location: Robert Wise Consulting, Station Square 1, Suite 104,
37 N. Valley Road, Paoli PA 19301

PENNSYLVANIA HISTORIC RESOURCE SURVEY FORM - DATA SHEET

Pennsylvania Historical and Museum Commission, Bureau for Historic Preservation

89B

IDENTIFICATION AND LOCATION

Survey Code: 021 Tax Parcel/Other No.: 66-00-1789-00-8 Block Unit #005-003

County: 1. Montgomery 091 2.

Municipality: 1. Whitpain Township 2.

Address: 938 DeKalb Pike Historic Name:

Other Name:

Owner Name/Address: Rodman B. Lentz & F.M. 938 DeKalb Pike, Center Square PA 19422

Owner Category: Private Public-local Public-state Public-federal

Resource Category: Building District Site Structure Object

Number/Approximate Number of Resources Covered by This Form: 1

USGS Quad: 1. Lansdale 2.

UTM A. _____ C. _____

References: B. _____ D. _____

HISTORIC AND CURRENT FUNCTIONS

Historic Function Category: **Subcategory:** **Code:**

A. Residence Dwelling _____

B. _____

C. _____

D. _____

Particular Type: A. _____

B. _____

C. _____

D. _____

Current Function Category: **Subcategory:** **Code:**

A. Single Family Residence Dwelling _____

B. _____

C. _____

D. _____

PHYSICAL DESCRIPTION

Architectural Classification: A. Federal _____

B. _____ C. _____

D. Other: _____

Exterior Materials: Foundation _____ Roof _____

Walls stucco _____ Walls _____

Other _____ Other _____

Structural System: 1. _____ 2. _____

Width 3 bay _____ Depth _____ Stories/Height 2.5 _____

HISTORICAL INFORMATION

Year Built: ca. 1820 Additions/Alterations Dates: ca. ca.
Basis for Dating: x Documentary Physical
Explain: Tax records

Cultural/Ethnic Affiliation: 1. _____ 2. _____ Associated Individuals: 1. _____ 2.
Associated Events: 1. _____ 2. _____ Architects/Engineers: 1. _____ 2.
Builders: 1. _____ 2.

MAJOR BIBLIOGRAPHICAL REFERENCES

PREVIOUS SURVEY, DETERMINATIONS

EVALUATION (Survey Director/Consultants Only)

Individual NR Potential: Yes x No Context(s): _____
Contributes to Potential District Yes No District Name/Status: _____

Classification: The resource has no significant features and is Class II.

THREATS

Threats: x 1. None 2. Public Development 3. Private Development 4. Neglect 5. Other

Explain:

SURVEYOR INFORMATION

Surveyor Name/Title: Robert Wise Date: 6/16/2000
Project Name: Whitpain Township Historic Resource Survey
Organization: Robert Wise Consulting/Whitpain Township Telephone: (610) 722-5818
Street and No.: Station Square 1, Suite 104, 37 North Valley Road
City, State: Paoli, Pa Zip Code: 19301
Additional Survey Documentation: n/a
Associated Survey Codes: n/a

PENNSYLVANIA HISTORICAL RESOURCE SURVEY FORM
NARRATIVE SHEET 89C

Pennsylvania Historical and Museum Commission
Bureau for Historic Preservation

Survey Code: 021 Tax Parcel/Other No.: 66-00-1789-00-8 Block Unit #005-003
County: Montgomery 091 Municipality: Whitpain Township
Address: 938 DeKalb Pike
Historic/Other Name:

PHYSICAL DESCRIPTION:

This Federal style house consists of a 2.5 story, three bay wide core and numerous additions on the rear. The core is similar to 956 DeKalb. It consists of stucco over stone walls, a center entrance with transom and sidelights, an end gabled, asphalt shingle roof, and full length pent roof on the main facade. Two plain, brick, flush chimneys are located at the ends of the house. Fenestration includes 4x4 sash windows on the first and second levels, and 3x3 sash windows occupying the frieze band. The core measures 30'x20'.

The addition attached to the core is a two-story arrangement creating an overall cross-axial roof, and an ell-shape to the overall structure. It features a second story Victorian era porch running along the eastern side. Attached to the rear of the addition is a garage that opens to the east. Attached to the south side of that garage addition is another garage, also facing east.

The property is in excellent condition.

Classification: The resource has no significant features and is Class II.

938 DeKalb #1



938 DeKalb
#2



938 DeKalb #3

