

PENNSYLVANIA HISTORIC RESOURCE SURVEY FORM PHOTO/SITE PLAN SHEET

Pennsylvania Historic and Museum Commission

Bureau of Historic Preservation

Box 1026, Harrisburg, PA 17108-1026

Survey Code/Tax Parcel/Other No.: 009 / 66 00 00634-00-2 Block 022 Unit 033

County: Montgomery

Municipality: Whitpain Township

Address: 983 Butler Pike

Historic Name/Other Name:

SITE PLAN**PHOTO INFORMATION**

Number	Description of View	Direction of Camera
1	House – façade	
2		
3		
4		
5		
6		
Photographer Name: Robert Wise		Date: 1999
Negative Location: Robert Wise Consulting, Station Square 1, Suite 104, 37 N. Valley Road, Paoli PA 19301		

PENNSYLVANIA HISTORIC RESOURCE SURVEY FORM - DATA SHEET

Pennsylvania Historical and Museum Commission, Bureau for Historic Preservation

89B

IDENTIFICATION AND LOCATION

Survey Code: 009 Tax Parcel/Other No.: 66-00-00634-00-2 Block 022 Unit 033

County: 1. Montgomery 091 2.

Municipality: 1. Whitpain Township 2.

Address: 983 Butler Pike Historic Name: Wyntrust

Other Name:

Owner Name/Address: James Timothy & Lisa Silar 983 Butler Pike Blue Bell PA 19422

Owner Category: Private Public-local Public-state Public-federal

Resource Category: Building District Site Structure Object

Number/Approximate Number of Resources Covered by This Form: 4

USGS Quad: 1. Lansdale 2.

UTM A. _____ C. _____

References: B. _____ D. _____

HISTORIC AND CURRENT FUNCTIONS

Historic Function Category:

Subcategory:

Code:

A. _____

B. _____

C. _____

D. _____

Particular Type:

A. _____

B. _____

C. _____

D. _____

Current Function Category:

Subcategory:

Code:

A. _____

B. _____

C. _____

D. _____

PHYSICAL DESCRIPTION

Architectural Classification:

A. Victorian _____

B. _____

C. _____

D. _____

Exterior Materials: Foundation _____

Roof _____ asphalt shingles

Walls _____ shingle _____

Walls _____

Other _____

Other _____

Structural System: 1. _____ 2. _____

Width _____ Depth _____ Stories/Height 2.5 _____

HISTORICAL INFORMATION

Year Built: ca. 1880 Additions/Alterations Dates: ca. ca.
Basis for Dating: x Documentary Physical
Explain: Tax records

Cultural/Ethnic Affiliation: 1. _____ 2. _____ Associated Individuals: 1. _____ 2.
Associated Events: 1. _____ 2. _____ Architects/Engineers: 1. _____ 2.
Builders: 1. _____ 2.

MAJOR BIBLIOGRAPHICAL REFERENCES

PREVIOUS SURVEY, DETERMINATIONS

EVALUATION (Survey Director/Consultants Only)

Individual NR Potential: Yes x No Context(s): _____
Contributes to Potential District Yes No District Name/Status: _____

Classification: Wyntrust appears to be intact and a rather rare form of architecture in the Township, Class II.

THREATS

Threats: x 1. None 2. Public Development 3. Private Development 4. Neglect 5. Other

Explain:

SURVEYOR INFORMATION

Surveyor Name/Title: Robert Wise Date: 6/16/2000
Project Name: Whitpain Township Historic Resource Survey
Organization: Robert Wise Consulting/Whitpain Township Telephone: (610) 722-5818
Street and No.: Station Square 1, Suite 104, 37 North Valley Road
City, State: Paoli, Pa Zip Code: 19301
Additional Survey Documentation: n/a
Associated Survey Codes: n/a

PENNSYLVANIA HISTORICAL RESOURCE SURVEY FORM
NARRATIVE SHEET 89C

Pennsylvania Historical and Museum Commission
Bureau for Historic Preservation

Survey Code: 009 Tax Parcel/Other No.: 66-00-00634-00-2 Block 022 Unit 033
County: Montgomery 091 Municipality: Whitpain Township
Address: 983 Butler Pike
Historic/Other Name: Wyntrust

PHYSICAL DESCRIPTION:

“Wyntrust” is an example of Victorian architecture. It is a 2½ story house with end gables and a projecting gable forming a gable roof (asphalt shingles). A single end chimney punctures one of the gable ends. The roof and the walls are covered with wood shingles, and two small dormers appear on the façade. The walls flare over the first floor. Windows are double sash. A one story wrap-around porch with a hipped roof covers most of the façade of the house; it is supported by several columns. A balcony is located in the center over the front porch on the main façade.

Associated resources. (1) Frame garage on a stone foundation with shingle siding.
(2) Large stone gate post.
(3) Stuccoed gazebo.

Classification: Wyntrust appears to be intact and a rather rare form of architecture in the Township, Class II.

RECEIVED

OCT 23 2000

WHITPAIN TOWNSHIP

