

PENNSYLVANIA HISTORIC RESOURCE SURVEY FORM PHOTO/SITE PLAN SHEET

Pennsylvania Historic and Museum Commission

Bureau of Historic Preservation

Box 1026, Harrisburg, PA 17108-1026

Survey Code/Tax Parcel/Other No.: 025 / 66-00-01777-00-2 Block Unit #004-002,3

County: Montgomery

Municipality: Whitpain Township

Address: 998 DeKalb Pike

Historic Name/Other Name:

SITE PLAN**PHOTO INFORMATION****Direction of Camera**

Number	Description of View	Direction of Camera
1	House – façade	
2	House – rear	
3		
4		
5		
6		
Photographer Name:	Robert Wise	Date: 1999
Negative Location:	Robert Wise Consulting, Station Square 1, Suite 104, 37 N. Valley Road, Paoli PA 19301	

PENNSYLVANIA HISTORIC RESOURCE SURVEY FORM - DATA SHEET

Pennsylvania Historical and Museum Commission, Bureau for Historic Preservation

89B

IDENTIFICATION AND LOCATION

Survey Code: 025 Tax Parcel/Other No.: 66-00-01777-00-2 Block Unit #004-002,3

County: 1. Montgomery 091 2.

Municipality: 1. Whitpain Township 2.

Address: 998 DeKalb Pike Historic Name:

Other Name:

Owner Name/Address: Nan-Sue Farms 7214 Butler Pike Ambler PA 19002

Owner Category: Private Public-local Public-state Public-federal

Resource Category: Building District Site Structure Object

Number/Approximate Number of Resources Covered by This Form: 1

USGS Quad: 1. Lansdale 2.

UTM A. _____ C. _____

References: B. _____ D. _____

HISTORIC AND CURRENT FUNCTIONS

Historic Function Category: **Subcategory:** **Code:**

A. Residence Dwelling _____

B. _____

C. _____

D. _____

Particular Type: A. _____

B. _____

C. _____

D. _____

Current Function Category: **Subcategory:** **Code:**

A. Single Family Residence Dwelling _____

B. _____

C. _____

D. _____

PHYSICAL DESCRIPTION

Architectural Classification: A. Victorian _____

B. _____

D. _____

C. _____

Other: _____

Exterior Materials: Foundation _____

Roof _____ slate _____

Walls brick _____

Other _____

Other _____

Structural System: 1. _____ 2. _____

Width 2 bay _____ Depth _____ Stories/Height 2 _____

HISTORICAL INFORMATION

Year Built: ca. 1880 Additions/Alterations Dates: ca. ca.
Basis for Dating: x Documentary Physical
Explain: Tax records

Cultural/Ethnic Affiliation: 1. _____ 2. _____ Associated Individuals: 1. _____ 2.
Associated Events: 1. _____ 2. _____ Architects/Engineers: 1. _____ 2.
Builders: 1. _____ 2.

MAJOR BIBLIOGRAPHICAL REFERENCES

PREVIOUS SURVEY, DETERMINATIONS

EVALUATION (Survey Director/Consultants Only)

Individual NR Potential: Yes x No Context(s): _____
Contributes to Potential District Yes No District Name/Status: _____

Classification: This rather unique building is Class II.

THREATS

Threats: x 1. None 2. Public Development 3. Private Development 4. Neglect 5. Other

Explain:

SURVEYOR INFORMATION

Surveyor Name/Title: Robert Wise Date: 6/16/2000
Project Name: Whitpain Township Historic Resource Survey
Organization: Robert Wise Consulting/Whitpain Township Telephone: (610) 722-5818
Street and No.: Station Square 1, Suite 104, 37 North Valley Road
City, State: Paoli, Pa Zip Code: 19301
Additional Survey Documentation: n/a
Associated Survey Codes: n/a

PENNSYLVANIA HISTORICAL RESOURCE SURVEY FORM
NARRATIVE SHEET 89C

Pennsylvania Historical and Museum Commission
Bureau for Historic Preservation

Survey Code: 025 Tax Parcel/Other No.: 66-00-01777-00-2 Block Unit #004-002,3
County: Montgomery 091 Municipality: Whitpain Township
Address: 998 DeKalb Pike
Historic/Other Name:

PHYSICAL DESCRIPTION:

This Vernacular building with Victorian features is a 2 story, brick clad residence with a front-end gable, hipped slate roof. The foundation is cut stone. The window openings are segmented arch, yet the windows are regular 1x1 sash. The two bay wide building also has a brick, bay window with an octagonal shed roof. (This roof is all that remains of a porch roof that once occupied the entire front of the house and wrapped 2/3 of the way around the western side. (The porch, now roofless, continues to occupy wrap around this area.) A small gabled hood protects the front door entrance. The door also occupies a space under a segmental arch and flat transom. A corbelled brick chimney is located on the southern or rear end of the house. Also on the rear of the house is a single story, shed addition with German siding.

Classification: This rather unique building is Class II.

998 DeKalb
#1



998 DeKalb
#2

