

**PENNSYLVANIA HISTORIC RESOURCE SURVEY FORM PHOTO/SITE PLAN SHEET**

Pennsylvania Historic and Museum Commission  
Bureau of Historic Preservation  
Box 1026, Harrisburg, PA 17108-1026

Survey Code/Tax Parcel/Other No.: 162 / 66 00 08196 40 5 Block-Unit #019-055

County: Montgomery

Municipality: Whitpain Township

Address: 1069 Walton Road

Historic Name/Other Name: \_\_\_\_\_

**SITE PLAN**

**PHOTO INFORMATION**



Number	Description of View	Direction of Camera
1	House – façade (right)	
2	House – addition	
3		
4		
5		
6		
Photographer Name:	Robert Wise	Date: 1999
Negative Location:	Robert Wise Consulting, Station Square 1, Suite 104, 37 N. Valley Road, Paoli PA 19301	

# PENNSYLVANIA HISTORIC RESOURCE SURVEY FORM - DATA SHEET

Pennsylvania Historical and Museum Commission, Bureau for Historic Preservation

89B

## IDENTIFICATION AND LOCATION

Survey Code: 162 Tax Parcel/Other No.: 66 00 08196 40 5 Block Unit #019-055

County: 1. Montgomery 091 2.

Municipality: 1. Whitpain Township 2.

Address: 1069 Walton Road Historic Name:

Other Name:

Owner Name/Address: Bruce & Ingram Barner 1069 Walton Road Blue Bell PA 19422

Owner Category:  Private  Public-local  Public-state  Public-federal

Resource Category:  Building  District  Site  Structure  Object

Number/Approximate Number of Resources Covered by This Form: 2

USGS Quad: 1. Lansdale 2.

UTM A. \_\_\_\_\_ C. \_\_\_\_\_

References: B. \_\_\_\_\_ D. \_\_\_\_\_

## HISTORIC AND CURRENT FUNCTIONS

Historic Function Category: **Subcategory:** **Code:**

A. Residence 1815 3,925 SF Land 2.47 Acre Dwelling \_\_\_\_\_

B. \_\_\_\_\_

C. \_\_\_\_\_

D. \_\_\_\_\_

Particular Type: A. \_\_\_\_\_

B. \_\_\_\_\_

C. \_\_\_\_\_

D. \_\_\_\_\_

Current Function Category: **Subcategory:** **Code:**

A. Single Family Residence Dwelling \_\_\_\_\_

B. \_\_\_\_\_

C. \_\_\_\_\_

D. \_\_\_\_\_

## PHYSICAL DESCRIPTION

Architectural Classification: A. Federal \_\_\_\_\_

B. \_\_\_\_\_

D. \_\_\_\_\_

C. \_\_\_\_\_

Other: \_\_\_\_\_

Exterior Materials: Foundation \_\_\_\_\_ Roof standing seam tin roof \_\_\_\_\_

Walls stucco \_\_\_\_\_ Walls \_\_\_\_\_

Other \_\_\_\_\_ Other \_\_\_\_\_

Structural System: 1. \_\_\_\_\_ 2. \_\_\_\_\_

Width 4 bay \_\_\_\_\_ Depth \_\_\_\_\_ Stories/Height 3 \_\_\_\_\_

## HISTORICAL INFORMATION

Year Built: ca. 1815 Additions/Alterations Dates: ca. ca.  
Basis for Dating: x Documentary Physical  
Explain: Tax records

Cultural/Ethnic Affiliation: 1. \_\_\_\_\_ 2. \_\_\_\_\_ Associated Individuals: 1. \_\_\_\_\_ 2.  
Associated Events: 1. \_\_\_\_\_ 2. \_\_\_\_\_ Architects/Engineers: 1. \_\_\_\_\_ 2.  
Builders: 1. \_\_\_\_\_ 2.

## MAJOR BIBLIOGRAPHICAL REFERENCES

## PREVIOUS SURVEY, DETERMINATIONS

### EVALUATION (Survey Director/Consultants Only)

Individual NR Potential: Yes x No Context(s): \_\_\_\_\_  
Contributes to Potential District Yes No District Name/Status: \_\_\_\_\_

**Classification:** The large addition makes this house a Class II resource.

## THREATS

Threats: x 1. None 2. Public Development 3. Private Development 4. Neglect 5. Other

Explain:

## SURVEYOR INFORMATION

Surveyor Name/Title: Robert Wise Date: 6/16/2000  
Project Name: Whitpain Township Historic Resource Survey  
Organization: Robert Wise Consulting/Whitpain Township Telephone: (610) 722-5818  
Street and No.: Station Square 1, Suite 104, 37 North Valley Road  
City, State: Paoli, Pa Zip Code: 19301  
Additional Survey Documentation: n/a  
Associated Survey Codes: n/a

PENNSYLVANIA HISTORICAL RESOURCE SURVEY FORM  
NARRATIVE SHEET 89C

Pennsylvania Historical and Museum Commission  
Bureau for Historic Preservation

Survey Code: 162 Tax Parcel/Other No.: 66 00 08196 40 5 Block-Unit #019-055  
County: Montgomery 091 Municipality: Whitpain Township  
Address: 1069 Walton Road  
Historic/Other Name:

**PHYSICAL DESCRIPTION:**

This is an excellent specimen of Federal architecture. The core was built c. 1815 and a rear addition was constructed later. The core is a two and a half story, four bay, end-gable building clad in stucco. There are two interior end chimneys. Third floor windows are three over three double hung with shutters on the sides; all other windows are six over six double hung with shutters. A gabled entry porch rests on square un-fluted columns and pilasters.

The two story rear addition is composed of un-coursed stone. It has six over six double hung windows but no shutters. In the gable end is a fanlight. Unlike most rear additions, its gabled orientation parallels that of the core.

**Classification:** The large addition makes this house a Class II resource.

