

PENNSYLVANIA HISTORIC RESOURCE SURVEY FORM PHOTO/SITE PLAN SHEET

Pennsylvania Historic and Museum Commission

Bureau of Historic Preservation

Box 1026, Harrisburg, PA 17108-1026

Survey Code/Tax Parcel/Other No.:

085 / 66 00 05143 00 2 Block-Unit #014-022

County:

Montgomery

Municipality:

Whitpain Township

Address:

1175 Penlyn Blue Bell Pike

Historic Name/Other Name:

SITE PLAN

PHOTO INFORMATION



Number	Description of View	Direction of Camera
--------	---------------------	---------------------

1 House – facade (right)

2 House – facade and addition

3

4

5

6

Photographer Name: Robert Wise Date: 1999

Negative Location: Robert Wise Consulting, Station Square 1, Suite 104,
37 N. Valley Road, Paoli PA 19301

PENNSYLVANIA HISTORIC RESOURCE SURVEY FORM - DATA SHEET

Pennsylvania Historical and Museum Commission, Bureau for Historic Preservation

89B

IDENTIFICATION AND LOCATION

Survey Code: 085 Tax Parcel/Other No.: 66 00 05143 00 2 Block Unit #014-022

County: 1. Montgomery 091 2.

Municipality: 1. Whitpain Township 2.

Address: 1175 Penllyn Blue Bell Pike Historic Name:

Other Name:

Owner Name/Address: Kathryn Seel 1175 Penllyn Blue Bell Pike Blue Bell PA 19422

Owner Category: Private Public-local Public-state Public-federal

Resource Category: Building District Site Structure Object

Number/Aproximate Number of Resources Covered by This Form: 2

USGS Quad: 1. Lansdale 2.

UTM A. _____ C. _____

References: B. _____ D. _____

HISTORIC AND CURRENT FUNCTIONS

Historic Function Category: Subcategory: Code:

A. Residence 1742 1,952 SF Land 1.03 Acre Dwelling _____

B. _____

C. _____

D. _____

Particular Type: A. _____

B. _____

C. _____

D. _____

Current Function Category: Subcategory: Code:

A. Single Family Residence Dwelling _____

B. _____

C. _____

D. _____

PHYSICAL DESCRIPTION

Architectural Classification: A. Vernacular _____

B. _____

D. _____

Exterior Materials: Foundation _____ Roof _____ asphalt shingles _____

Walls _____ stucco _____

Other _____

Structural System: 1. _____ 2. _____

Width _____ Depth _____ Stories/Height _____ 2 _____

HISTORICAL INFORMATION

Year Built: ca. 1742 Additions/Alterations Dates: ca. ca.
Basis for Dating: x Documentary Physical
Explain: Tax records

Cultural/Ethnic Affiliation: 1. _____ 2. _____ Associated Individuals: 1. _____ 2.
Associated Events: 1. _____ 2. _____ Architects/Engineers: 1. _____ 2.
Builders: 1. _____ 2.

MAJOR BIBLIOGRAPHICAL REFERENCES

PREVIOUS SURVEY, DETERMINATIONS

EVALUATION (Survey Director/Consultants Only)

Individual NR Potential: Yes x No Context(s): _____
Contributes to Potential District Yes No District Name/Status:

Classification: This is a very old house in good condition, but it has been highly altered. It is a Class II resource.

THREATS

Threats: x 1. None 2. Public Development 3. Private Development 4. Neglect 5. Other

Explain:

SURVEYOR INFORMATION

Surveyor Name/Title: Robert Wise Date: 6/16/2000
Project Name: Whitpain Township Historic Resource Survey
Organization: Robert Wise Consulting/Whitpain Township Telephone: (610) 722-5818
Street and No.: Station Square 1, Suite 104, 37 North Valley Road
City, State: Paoli, Pa Zip Code: 19301
Additional Survey Documentation: n/a
Associated Survey Codes: n/a

PENNSYLVANIA HISTORICAL RESOURCE SURVEY FORM
NARRATIVE SHEET 89C

Pennsylvania Historical and Museum Commission
Bureau for Historic Preservation

Survey Code: 085 Tax Parcel/Other No.: 66 00 05143 00 2 Block-Unit #014-022
County: Montgomery 091 Municipality: Whitpain Township
Address: 1175 Penllyn Blue Bell Pike
Historic/Other Name:

PHYSICAL DESCRIPTION:

This house is an example of colonial Pennsylvania vernacular architecture. The original house was built c. 1742 and has had several additions. It is a two and a half story, three bay building with yellow stucco siding; interior chimneys appear at the gable ends. The end gable roof has asphalt shingles. Windows are six over six double-hung sash, but the shutters have been removed. An entrance hood has a triangular pediment broken at the bottom. Some evidence of the original pent roof is visible. There are several newer frame additions including one under construction that will double the size of the house..

Associated Resource: There is a carriage house associated with this house that is a two-bay frame building. (no photo)

Classification: This is a very old house in good condition, but it has been highly altered. It is a Class II resource.



