

PENNSYLVANIA HISTORIC RESOURCE SURVEY FORM PHOTO/SITE PLAN SHEET
Pennsylvania Historic and Museum Commission
Bureau of Historic Preservation
Box 1026, Harrisburg, PA 17108-1026

Survey Code/Tax Parcel/Other No.: 164 / 66-00-08221-00-2 Block Unit #019-017

County: Montgomery

Municipality: Whitpain Township

Address: 1330 Walton Road

Historic Name/Other Name:

SITE PLAN

PHOTO INFORMATION



Number	Description of View	Direction of Camera
1	House – façade	
2	House – addition	
3		
4		
5		
6		
Photographer Name: Robert Wise		Date: 1999
Negative Location: Robert Wise Consulting, Station Square 1, Suite 104, 37 N. Valley Road, Paoli PA 19301		

PENNSYLVANIA HISTORIC RESOURCE SURVEY FORM - DATA SHEET

Pennsylvania Historical and Museum Commission, Bureau for Historic Preservation

89B

IDENTIFICATION AND LOCATION

Survey Code: 164 Tax Parcel/Other No.: 66-00-08221-00-2 Block Unit #019-017

County: 1. Montgomery 091 2.

Municipality: 1. Whitpain Township 2.

Address: 1330 Walton Road Historic Name:

Other Name:

Owner Name/Address: John Lewis 1330 Walton Road Blue Bell PA 19422

Owner Category: Private Public-local Public-state Public-federal

Resource Category: Building District Site Structure Object

Number/Approximate Number of Resources Covered by This Form: 2

USGS Quad: 1. Lansdale 2.

UTM A. _____ C. _____

References: B. _____ D. _____

HISTORIC AND CURRENT FUNCTIONS

Historic Function Category: **Subcategory:** **Code:**

A. Residence Dwelling _____

B. _____

C. _____

D. _____

Particular Type: A. _____

B. _____

C. _____

D. _____

Current Function Category: **Subcategory:** **Code:**

A. Single Family Residence Dwelling _____

B. _____

C. _____

D. _____

PHYSICAL DESCRIPTION

Architectural Classification: A. Federal _____

B. _____ C. _____

D. _____ Other: _____

Exterior Materials: Foundation _____ Roof _____ asphalt shingles _____

Walls _____ stucco _____ Walls _____

Other _____ Other _____

Structural System: 1. _____ 2. _____

Width 3 bays _____ Depth _____ Stories/Height 2.5 _____

HISTORICAL INFORMATION

Year Built: _____ ca. _____ Additions/Alterations Dates: _____ ca. _____ ca. _____
Basis for Dating: Documentary Physical
Explain: Tax records

Cultural/Ethnic Affiliation: 1. _____ 2. _____ Associated Individuals: 1. _____ 2.
Associated Events: 1. _____ 2. _____ Architects/Engineers: 1. _____ 2.
Builders: 1. _____ 2.

MAJOR BIBLIOGRAPHICAL REFERENCES

PREVIOUS SURVEY, DETERMINATIONS

EVALUATION (Survey Director/Consultants Only)

Individual NR Potential: _____ Yes No Context(s): _____
Contributes to Potential District _____ Yes _____ No District Name/Status: _____

Classification: This house is in fair condition. The end addition and dormer make the house a Class II resource.

THREATS

Threats: 1. None 2. Public Development 3. Private Development 4. Neglect 5. Other

Explain:

SURVEYOR INFORMATION

Surveyor Name/Title: Robert Wise Date: 6/16/2000
Project Name: Whitpain Township Historic Resource Survey
Organization: Robert Wise Consulting/Whitpain Township Telephone: (610) 722-5818
Street and No.: Station Square 1, Suite 104, 37 North Valley Road
City, State: Paoli, Pa Zip Code: 19301
Additional Survey Documentation: n/a
Associated Survey Codes: n/a

PENNSYLVANIA HISTORICAL RESOURCE SURVEY FORM
NARRATIVE SHEET 89C

Pennsylvania Historical and Museum Commission
Bureau for Historic Preservation

Survey Code: 164 Tax Parcel/Other No.: 66-00-08221-00-2 Block Unit #019-017
County: Montgomery 091 Municipality: Whitpain Township
Address: 1330 Walton Road
Historic/Other Name:

PHYSICAL DESCRIPTION:

This is a Federal style house with two additions. The core is a three-bay, two and a half story end gable house with one interior end chimney. It has an end gable asphalt shingle roof and molded cornice. A wall dormer has been added; this gabled dormer has two six over six double-hung windows with shutters. Two other items of note are the pent roof and Greek Revival-style door framing (the door jambs are fluted pilasters). The first addition is one-story, gabled, with eight over eight windows double hung with shutters. The rear addition is two story on a perpendicular axis.

Associated Resource: Garage: There is a contributing, two story frame garage building associated with this house.

Classification: This house is in fair condition. The end addition and dormer make the house a Class II resource.

