

PENNSYLVANIA HISTORIC RESOURCE SURVEY FORM PHOTO/SITE PLAN SHEET

Pennsylvania Historic and Museum Commission

Bureau of Historic Preservation

Box 1026, Harrisburg, PA 17108-1026

Survey Code/Tax Parcel/Other No.: 186 / 66 00 06673 00 2 Block Unit #009-026

County: Montgomery

Municipality: Whitpain Township

Address: 1433 Skippack Pike

Historic Name/Other Name:

SITE PLAN

PHOTO INFORMATION



Number	Description of View	Direction of Camera
1	House – façade	
2	House – façade	
3		
4		
5		
6		
Photographer Name: Robert Wise		Date: 1999
Negative Location: Robert Wise Consulting, Station Square 1, Suite 104, 37 N. Valley Road, Paoli PA 19301		

PENNSYLVANIA HISTORIC RESOURCE SURVEY FORM - DATA SHEET

Pennsylvania Historical and Museum Commission, Bureau for Historic Preservation

89B

IDENTIFICATION AND LOCATION

Survey Code: 186 Tax Parcel/Other No.: 66 00 06673 00 2 Block Unit #009-026

County: 1. Montgomery 091 2.

Municipality: 1. Whitpain Township 2.

Address: 1433 Skippack Pike Historic Name:

Other Name:

Owner Name/Address: Robert & Benita Grill 20 Sara Lane, Limerick PA 19468

Owner Category: Private Public-local Public-state Public-federal

Resource Category: Building District Site Structure Object

Number/Approximate Number of Resources Covered by This Form: 1

USGS Quad: 1. Lansdale 2.

UTM A. _____ C. _____

References: B. _____ D. _____

HISTORIC AND CURRENT FUNCTIONS

Historic Function Category: Subcategory: **Code:**

A. Residence Dwelling _____

B. _____

C. _____

D. _____

Particular Type: A. _____

B. _____

C. _____

D. _____

Current Function Category: Subcategory: **Code:**

A. Residence Dwelling _____

B. _____

C. _____

D. _____

PHYSICAL DESCRIPTION

Architectural Classification: A. Bungalow _____

B. _____

D. _____

C. _____

Other: _____

Exterior Materials: Foundation stone _____ Roof _____

Walls stucco _____ Walls _____

Other _____ Other _____

Structural System: 1. _____ 2. _____

Width 3 Depth _____ Stories/Height 2 _____

HISTORICAL INFORMATION

Year Built: ___ ca. _____ Additions/Alterations Dates: ___ ca. ___ ca. ___

Basis for Dating: ___ Documentary ___ Physical

Explain:

Cultural/Ethnic Affiliation: 1. _____ 2. _____ Associated Individuals: 1. _____ 2.

Associated Events: 1. _____ 2. _____ Architects/Engineers: 1. _____ 2.

Builders: 1. _____ 2.

MAJOR BIBLIOGRAPHICAL REFERENCES

PREVIOUS SURVEY, DETERMINATIONS

EVALUATION (Survey Director/Consultants Only)

Individual NR Potential: Yes No Context(s): _____

Contributes to Potential District Yes No District Name/Status: Center Square HD 118

Classification: Although recognized as a contributing resource in the Center Square Historic District (determined eligible for the National Register), this resource is individually ineligible for Class I and thus is a Class II resource.

THREATS

Threats: 1. None 2. Public Development 3. Private Development 4. Neglect 5. Other

Explain:

SURVEYOR INFORMATION

Surveyor Name/Title: Robert Wise Date: 6/16/2000

Project Name: Whitpain Township Historic Resource Survey

Organization: Robert Wise Consulting/Whitpain Township Telephone: (610) 722-5818

Street and No.: Station Square 1, Suite 104, 37 North Valley Road

City, State: Paoli, Pa Zip Code: 19301

Additional Survey Documentation: n/a

Associated Survey Codes: n/a

PENNSYLVANIA HISTORICAL RESOURCE SURVEY FORM
NARRATIVE SHEET 89C

Pennsylvania Historical and Museum Commission
Bureau for Historic Preservation

Survey Code: 186 Tax Parcel/Other No.: 66 00 06673 00 2 Block Unit #009-026
County: Montgomery 091 Municipality: Whitpain Township

Address: 1433 Skippack Pike

Historic/Other Name:

PHYSICAL DESCRIPTION:

This house was built in the Bungalow tradition with two additions. The core is a 1.5 story, three bay house clad in dark colored stucco with a one-story wrap-around porch. There is a window in the front gable and a double window in the right bay on the first floor. Frames around the door and windows have a simple profile. The door has a series of glass panes rather than panels. The standard porch rests on columns composed of a stone base supporting short square columns. The exposed rafters on the porch are partially hidden by the gutter. A wood railing connects the stone column bases to help enclose the porch. An addition to the side of the house is a one-story element with smaller windows. It is clad in stucco of a light brown color and possibly replaces a portion of the original wrap-around porch. A second addition was the construction of monitor dormers to enlarge the second floor. The rafter ends of the roof are exposed over the monitor dormers, reflecting the original style of the house.

Classification: Although recognized as a contributing resource in the Center Square Historic District (determined eligible for the National Register), this resource is individually ineligible for Class I and thus is a Class II resource.



