

PENNSYLVANIA HISTORIC RESOURCE SURVEY FORM PHOTO/SITE PLAN SHEET

Pennsylvania Historic and Museum Commission

Bureau of Historic Preservation

Box 1026, Harrisburg, PA 17108-1026

Survey Code/Tax Parcel/Other No.: 66 00 08176 00 2 Block-Unit #019-001

County: Montgomery

Municipality: Whitpain Township

Address: 1451 Walton Road

Historic Name/Other Name: _____

SITE PLAN

PHOTO INFORMATION



Number	Description of View	Direction of Camera
1	House – façade (right)	
2	House – façade (left)	
3	Barn	
4		
5		
6		
Photographer Name:	Robert Wise	Date: 1999
Negative Location:	Robert Wise Consulting, Station Square 1, Suite 104, 37 N. Valley Road, Paoli PA 19301	

PENNSYLVANIA HISTORIC RESOURCE SURVEY FORM - DATA SHEET

Pennsylvania Historical and Museum Commission, Bureau for Historic Preservation

89B

IDENTIFICATION AND LOCATION

Survey Code: Walton Road #2 (15.6) Tax Parcel/Other No.: 66 00 08176 00 2 Block Unit #019-001

County: 1. Montgomery 091 2.

Municipality: 1. Whitpain Township 2.

Address: 1451 Walton Road Historic Name:

Other Name:

Owner Name/Address: Charles L. & Phyllis C. Springer 1451 Walton Rd Blue Bell PA 19422

Owner Category: Private Public-local Public-state Public-federal

Resource Category: Building District Site Structure Object

Number/Approximate Number of Resources Covered by This Form: 2

USGS Quad: 1. Lansdale 2.

UTM A. _____ C. _____

References: B. _____ D. _____

HISTORIC AND CURRENT FUNCTIONS

Historic Function Category: **Subcategory:** **Code:**

A. Residence 1832 1,305 SF Land 0.58 Acre Dwelling _____

B. _____

C. _____

D. _____

Particular Type: A. _____

B. _____

C. _____

D. _____

Current Function Category: **Subcategory:** **Code:**

A. Single Family Residence Dwelling _____

B. _____

C. _____

D. _____

PHYSICAL DESCRIPTION

Architectural Classification: A. Vernacular _____

B. _____

D. Other: _____

Exterior Materials: Foundation _____ Roof _____

Walls stone _____ Walls _____

Other _____ Other _____

Structural System: 1. _____ 2. _____

Width 2 bay / 25 feet Depth 15 feet Stories/Height 2 _____

HISTORICAL INFORMATION

Year Built: ca. 1832 Additions/Alterations Dates: ca. ca.
Basis for Dating: x Documentary Physical
Explain: Tax records

Cultural/Ethnic Affiliation: 1. _____ 2. _____ Associated Individuals: 1. _____ 2.
Associated Events: 1. _____ 2. _____ Architects/Engineers: 1. _____ 2.
Builders: 1. _____ 2.

MAJOR BIBLIOGRAPHICAL REFERENCES

PREVIOUS SURVEY, DETERMINATIONS

EVALUATION (Survey Director/Consultants Only)

Individual NR Potential: Yes x No Context(s): _____
Contributes to Potential District Yes No District Name/Status: _____

Classification: While the house is in excellent condition, the minor alterations make it a Class II resource.

THREATS

Threats: x 1. None 2. Public Development 3. Private Development 4. Neglect 5. Other

Explain:

SURVEYOR INFORMATION

Surveyor Name/Title: Robert Wise Date: 6/16/2000
Project Name: Whitpain Township Historic Resource Survey
Organization: Robert Wise Consulting/Whitpain Township Telephone: (610) 722-5818
Street and No.: Station Square 1, Suite 104, 37 North Valley Road
City, State: Paoli, Pa Zip Code: 19301
Additional Survey Documentation: n/a
Associated Survey Codes: n/a

PENNSYLVANIA HISTORICAL RESOURCE SURVEY FORM
NARRATIVE SHEET 89C

Pennsylvania Historical and Museum Commission
Bureau for Historic Preservation

Survey Code: Walton Road #2 (15.6) Tax Parcel/Other No.: 66 00 08176 00 2 Block-Unit #019-001

County: Montgomery 091 Municipality: Whitpain Township

Address: 1451 Walton Road

Historic/Other Name:

PHYSICAL DESCRIPTION:

This house is a good example of vernacular architecture. It is a two and a half story, two bay gable-end house, 15 x 25 feet, composed of fieldstone. The roof is asphalt shingles; there is one exterior end chimney and one interior end chimney. Windows on the façade (replacement) are six over six double hung with no shutters; two windows in the gable are arched on one corner. The hood over the door is a gabled element supported by simple braces.

Associated Resource:

Accompanying this house is a board and batten carriage shed with a cross-gable roof and shed additions.

Classification: While the house is in excellent condition, the alterations (including the gable windows) make it a Class II resource.



